

Table of Contents

	<u>NAME OF SITE</u>	<u>SITE NO.</u>	<u>NEGATIVE FILE NO.</u>
1	Burt Nichols Place	1106-16	82-A-123
2	Griffith House	1106-17	82-A-123
3	Powers House	1106-18	82-A-123
4	Webster House	1106-19	82-A-124
5	House	1106-20	82-A-124
6	Congregational Church Parsonage	1106-21	82-A-244
7	School House	1106-22	89-A-92; 83-A-39
8	Ricketts House	1106-23	83-A-392; 89-A-93
9	Kievit House	1106-24	83-A-392; 89-A-93
10	Smith House	1106-25	83-A-392; 89-A-93
11	Croce Camp	1106-27	83-A-392; 89-A-93
12	Staples Farm	1106-28	83-A-391; 89-A-93
13	House	1106-29	83-A-392; 89-A-93
14	House	1106-30	89-A-93
15	House	1106-31	89-A-93
16	Long-Blinn Farm	1106-32	89-A-94; 83-A-392
17	Bromley-Fernen Farm	1106-34	83-A-389; 89-A-95
18	Macheski House	1106-35	83-A-391; 89-A-95
19	House	1106-36	83-A-389; 89-A-94
20	Campbell-Billings House	1106-37	83-A-389; 89-A-94
21	Yrskha House	1106-38	89-A-94
22	Warner-Kapuska House	1106-39	89-A-94

	<u>NAME OF SITE</u>	<u>SITE NO.</u>	<u>NEGATIVE FILE NO.</u>
23	Vermont Marble Co Worker's Housing	1106-40	89-A-94
24	Millard House	1106-41	83-A-388; 89-A-92
25	House	1106-42	83-A-388; 89-A-92
26	House	1106-43	83-A-392; 89-A-92
27	House	1106-45	83-A-388; 89-A-92
28	House	1106-46	83-A-388; 89-A-92
29	House	1106-47	83-A-388; 89-A-173
30	Rotiman House	1106-48	89-A-95
31	Neuman House	1106-49	89-A -95
32	Feltz-Ihasz Barn	1106-50	89-A-95
33	Lewis Barn	1106-51	89-A-95
34	Fiske-Taconic Foundation	1106-52	83-A-392; 89-A-95
35	Hilliard House-Taconic Foundation	1106-53	83-A-389; 89-A-95
36	Herrick-Taconic Foundation	1106-54	89-A-95
37	Coburn House	1106-55	83-A-389; 89-A-93
38	Danby Four Corners <i>STORE</i>	1106-57	83-A-389; 89-A-93
39	Loomis Barn	1106-58	83-A-93
40	Danby Town Hall	1106-59	83-A-389; 89-A-93
41	Gates House	1106-60	83-A-391; 89-A-93
42	King House	1106-61	85-A-569; 89-A-94

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

COUNTY:	Rutland
TOWN:	Danby
LOCATION:	West side of South Main Street just south of 1106-17.
COMMON NAME:	Burt Nichols Place
FUNCTIONAL TYPE:	Residence
OWNER:	
ADDRESS:	
ACCESSIBILITY TO PUBLIC:	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE:	Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>

GENERAL DESCRIPTION:

Structural System

- Foundation: Stone Brick Concrete Concrete Block
- Wall Structure
 - Wood Frame: Post & Beam Balloon
 - Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - Iron d. Steel e. Other:
- Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Shingle Brick Veneer Stone Veneer Bonding Pattern: Other:
- Roof Structure
 - Truss: Wood Iron Steel Concrete
 - Other:
- Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
- Engineering Structure:
- Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 2½

Number of Bays: 2 x 3

Approximate Dimensions: 30' x 30'

Entrance Location: Right front

SURVEY NUMBER:

1106-16

NEGATIVE FILE NUMBER:

82-A-123

UTM REFERENCES:

Zone/Easting/Northing

18 / 662375 / 4800600

U.S.G.S. QUAD. MAP:

Wallingford Quad 15'

PRESENT FORMAL NAME:

ORIGINAL FORMAL NAME:

Nichols House

PRESENT USE: Residence

ORIGINAL USE: Residence

ARCHITECT/ENGINEER:

Unknown

BUILDER/CONTRACTOR:

Unknown

PHYSICAL CONDITION OF STRUCTURE:

Excellent Good
Fair Poor

STYLE: Vernacular Colonial Revival

DATE BUILT:

c.1910

THREAT TO STRUCTURE:

No Threat Zoning Roads
Development Deterioration
Alteration Other:

LOCAL ATTITUDES:

Positive Negative
Mixed Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

Four Square plan and massing. Clapboards on first floor, shingles on second, "Craftsman" rubble foundation, slate roof Colonial Revival porch spans front facade. It includes Tuscan columns that support a wide entablature, balustrade, pediment over center. Main block detailed with cornice that has frieze board and large dentils; beltcourse and watertable. Large picture window on front, remaining 1/1, some paired. Rear gabled wing detailed similarly as main block - Modern entry porch, attached wing.

RELATED STRUCTURES: (Describe)


Detached shed

STATEMENT OF SIGNIFICANCE:

The Danby Marble Industry experienced a revival during the early years of this century. The prosperity this brought caused construction of several residences in and near the village. This unaltered well-preserved structure is an example of one of these houses. Its simple box-like four square mass has unique Colonial Revival and Craftsman style flourishes.

REFERENCES:

MAP: (Indicate North, in Circle)



SURROUNDING ENVIRONMENT:

Open Land Woodland
 Scattered Buildings
 Moderately Built Up
 Densely Built Up
 Residential Commercial
 Agricultural Industrial
 Roadside Strip Development
 Other:

RECORDED BY:

Gina Campoli

ORGANIZATION:

Division for Historic Preservation

DATE RECORDED:

July 1982



82-A-123

Vt. Div. for Historic Preservation
Rutland Danby 7/82
Burt Nicholls Place, 1106-16 NW
82-A-123 Gina Campoli

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

COUNTY: Rutland
TOWN: Danby
LOCATION: West side of S. Main Street South of Danby Village and 1106-7.
COMMON NAME:
FUNCTIONAL TYPE: Residence
OWNER: Richard Griffith ADDRESS: Danby VT 05739
ACCESSIBILITY TO PUBLIC: Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE: Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>

GENERAL DESCRIPTION:

Structural System

- Foundation: Stone Brick Concrete Concrete Block
- Wall Structure
 - Wood Frame: Post & Beam Balloon
 - Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - Iron d. Steel e. Other:
- Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Shingle Brick Veneer Stone Veneer
Bonding Pattern: Other:
- Roof Structure
 - Truss: Wood Iron Steel Concrete
 - Other:
- Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
- Engineering Structure:
- Other:

Appendages: Porches Towers Cupolas Dormers Chimneys
Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel
Jerkinhead Saw Tooth With Monitor With Bellcast
With Parapet With False Front Other:

Number of Stories: 1 1/2
Number of Bays: 5 x 2 Entrance Location: Center eaves side
Approximate Dimensions: 30' x 25'

SURVEY NUMBER: 1106-17
NEGATIVE FILE NUMBER: 82-A-123
UTM REFERENCES: Zone/Easting/Northing 18 / 662375 / 4800650
U.S.G.S. QUAD. MAP: Wallingford Quad 15'
PRESENT FORMAL NAME: Griffith House
ORIGINAL FORMAL NAME:
PRESENT USE: Residence
ORIGINAL USE: Residence
ARCHITECT/ENGINEER: Unknown
BUILDER/CONTRACTOR: Unknown
PHYSICAL CONDITION OF STRUCTURE: Excellent <input type="checkbox"/> Good <input checked="" type="checkbox"/> Fair <input type="checkbox"/> Poor <input type="checkbox"/>
STYLE: Late Greek Revival with Picturesque
DATE BUILT: Queen Anne elements c.1875

THREAT TO STRUCTURE: No Threat <input checked="" type="checkbox"/> Zoning <input type="checkbox"/> Roads <input type="checkbox"/> Development <input type="checkbox"/> Deterioration <input type="checkbox"/> Alteration <input type="checkbox"/> Other:	LOCAL ATTITUDES: Positive <input checked="" type="checkbox"/> Negative <input type="checkbox"/> Mixed <input type="checkbox"/> Other:
---	---

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

Classic Cottage with steeply pitched central wall dormer and high kneewall. Porch spans front includes chamfered posts with undersized scroll brackets, clapboard filled rail and clapboard skirt. Main block detailed with entablature and cornice with returns. Entrance flanked by large scale pilasters with entablature above. 2 x 2 sash with slight lip molding. Rear 1½ story ell and shed with shed roofed addition includes detailed rear porch w/chamfered posts and brackets.

RELATED STRUCTURES: (Describe)


Clapboarded gabled garage, 1½ stories. Sliding garage doors on east gable end.

STATEMENT OF SIGNIFICANCE:

Restrained Greek Revival details and a Classic Cottage form with a high kneewall indicate this is a late Greek style house. It is typical of style's manifestation in Vermont when it was long over in other parts of the country. The picturesque gable is rare in Danby.

REFERENCES:

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

Open Land Woodland
Scattered Buildings
Moderately Built Up
Densely Built Up
Residential Commercial
Agricultural Industrial
Roadside Strip Development
Other:

RECORDED BY:

Gina Campoli

ORGANIZATION:

Division for Historic Preservation

DATE RECORDED:

July 1982



82-A-123

Vt. Div. for Historic Preservation
Rutland Danby 7/82
Giffith House, 1106-17 W
82-A-123 Gina Campoli

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

COUNTY: Rutland
TOWN: Danby
LOCATION: West side of South Main Street
just south of the Melody Inn 1106-1, #45.
COMMON NAME:
FUNCTIONAL TYPE: Residence
OWNER: H. A. Powers
ADDRESS: Danby, VT 05739
ACCESSIBILITY TO PUBLIC:
Yes No Restricted
LEVEL OF SIGNIFICANCE:
Local State National

GENERAL DESCRIPTION:
Structural System
1. Foundation: Stone Brick Concrete Concrete Block
2. Wall Structure
a. Wood Frame: Post & Beam Balloon
b. Load Bearing Masonry: Brick Stone Concrete
Concrete Block
c. Iron d. Steel e. Other:
3. Wall Covering: Clapboard Board & Batten Wood Shingle
Shiplap Novelty Asbestos Shingle Sheet Metal
Aluminum Asphalt Shingle Brick Veneer Stone Veneer
Bonding Pattern: Other:
4. Roof Structure
a. Truss: Wood Iron Steel Concrete
b. Other:
5. Roof Covering: Slate Wood Shingle Asphalt Shingle
Sheet Metal Built Up Rolled Tile Other:
6. Engineering Structure:
7. Other:
Appendages: Porches Towers Cupolas Dormers Chimneys
Sheds Ells Wings Bay Window Other:
Roof Style: Gable Hip Shed Flat Mansard Gambrel
Jerkinhead Saw Tooth With Monitor With Bellcast
With Parapet With False Front Other:
Number of Stories: 1½
Number of Bays: 3 x 2
Approximate Dimensions: 20' x 15'

SURVEY NUMBER:
1106-18
NEGATIVE FILE NUMBER:
82-A-123
UTM REFERENCES:
Zone/Easting/Northing
18 / 662375 / 4800800
U.S.G.S. QUAD. MAP:
Wallingford Quad 15'
PRESENT FORMAL NAME:
Powers House
ORIGINAL FORMAL NAME:
PRESENT USE: Residence
ORIGINAL USE: Residence
ARCHITECT/ENGINEER:
Unknown
BUILDER/CONTRACTOR:
Unknown
PHYSICAL CONDITION OF STRUCTURE:
Excellent Good
Fair Poor
STYLE: Vernacular with Queen Anne porch
DATE BUILT:
c.1885

THREAT TO STRUCTURE:
No Threat Zoning Roads
Development Deterioration
Alteration Other:

LOCAL ATTITUDES:
Positive Negative
Mixed Other:

Entrance Location: Off-center right
of eaves side.

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

Simple gable form and mass with a shed roofed wing on the north gable end. Aluminum siding hides any detail on the main block. Porch across front has chamfered posts and scroll brackets.


RELATED STRUCTURES: (Describe)

STATEMENT OF SIGNIFICANCE:

Although aluminum siding hides any detail that may have decorated this cottage, the basic form is unaltered. The porch retains some Queen Anne features.

REFERENCES:

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

Open Land Woodland
Scattered Buildings
Moderately Built Up
Densely Built Up
Residential Commercial
Agricultural Industrial
Roadside Strip Development
Other:

RECORDED BY:
Gina Campoli

ORGANIZATION:
Division for Historic Preservation

DATE RECORDED:
July 1982



82-A-123

Vt. Div. for Historic Preservation
Rutland Danby Village 7/82
Powers House, 1106-18 NW
82-A-123 Gina Campoli

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

COUNTY: Rutland
TOWN: Danby
LOCATION: East side of S. Main Street,
just south of Danby Village and the
Congregational Church.
COMMON NAME:
FUNCTIONAL TYPE: Residence
OWNER: Ray and Grace Webster
ADDRESS: Danby, VT 05739
ACCESSIBILITY TO PUBLIC:
Yes No Restricted
LEVEL OF SIGNIFICANCE:
Local State National

GENERAL DESCRIPTION:
Structural System
1. Foundation: Stone Brick Concrete Concrete Block
2. Wall Structure
a. Wood Frame: Post & Beam Balloon
b. Load Bearing Masonry: Brick Stone Concrete
Concrete Block
c. Iron d. Steel e. Other:
3. Wall Covering: Clapboard Board & Batten Wood Shingle
Shiplap Novelty Asbestos Shingle Sheet Metal
Aluminum Asphalt Shingle Brick Veneer Stone Veneer
Bonding Pattern: Other:
4. Roof Structure
a. Truss: Wood Iron Steel Concrete
b. Other:
5. Roof Covering: Slate Wood Shingle Asphalt Shingle
Sheet Metal Built Up Rolled Tile Other:
6. Engineering Structure:
7. Other:
Appendages: Porches Towers Cupolas Dormers Chimneys
Sheds Ells Wings Bay Window Other:
Roof Style: Gable Hip Shed Flat Mansard Gambrel
Jerkinhead Saw Tooth With Monitor With Bellcast
With Parapet With False Front Other:
Number of Stories: 2½
Number of Bays: 3 x 2 Entrance Location: Right of Center
Approximate Dimensions: 28' x 20' front eaves side.

SURVEY NUMBER:
1106-19
NEGATIVE FILE NUMBER:
82-A-124
UTM REFERENCES:
Zone/Easting/Northing
18 / 662375 / 4800750
U.S.G.S. QUAD. MAP:
Wallingford Quad 15'
PRESENT FORMAL NAME:
Webster House
ORIGINAL FORMAL NAME:
PRESENT USE: Residence
ORIGINAL USE: Residence
ARCHITECT/ENGINEER:
Unknown
BUILDER/CONTRACTOR:
Unknown
PHYSICAL CONDITION OF STRUCTURE:
Excellent Good
Fair Poor
STYLE: Vernacular Bungaloid with Crafts-
DATE BUILT: c.1920 man detail

THREAT TO STRUCTURE:
No Threat Zoning Roads
Development Deterioration
Alteration Other:
LOCAL ATTITUDES:
Positive Negative
Mixed Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

Basic Georgian plan with a projecting central pavilion; side entry porch on north gable end and rear shed roofed porch and entry. Pavilion incorporates a first floor porch with square columns and stucco skirt. Small half circle vent in peak of pavilion gable. Bay window front facade right of pavilion. Field stone rubble foundation and south gable wall chimney and interior chimney stucco walls, slate roof. 3/1 sash and small kneewall windows on the front facade.

RELATED STRUCTURES: (Describe)


Garage with one bay gable end swinging doors. Novelty board siding. Exposed rafter tails. c.1920

STATEMENT OF SIGNIFICANCE:

This house has a somewhat traditional form, yet incorporates a unique combination of features that includes the use of stucco as a wall covering, a rubble foundation and chimneys and 3/1 sash.

REFERENCES:

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Gina Campoli

ORGANIZATION:

Division for Historic Preservation

DATE RECORDED:

July 1982



82-A-124

Vt. Div. for Historic Preservation
Rutland Danby 7/82
Webster House, 1106-19 E
82-A-124 Gina Campoli

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

COUNTY:	Rutland
TOWN:	Danby
LOCATION:	East side of S. Main Street, south of 1106-19 and Danby Village.
COMMON NAME:	
FUNCTIONAL TYPE:	Residence
OWNER:	
ADDRESS:	
ACCESSIBILITY TO PUBLIC:	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE:	Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>

GENERAL DESCRIPTION:	
Structural System	
1. Foundation:	Stone <input type="checkbox"/> Brick <input checked="" type="checkbox"/> Concrete <input type="checkbox"/> Concrete Block <input type="checkbox"/>
2. Wall Structure	
a. Wood Frame:	Post & Beam <input type="checkbox"/> Balloon <input checked="" type="checkbox"/>
b. Load Bearing Masonry:	Brick <input type="checkbox"/> Stone <input type="checkbox"/> Concrete <input type="checkbox"/> Concrete Block <input type="checkbox"/>
c. Iron <input type="checkbox"/> d. Steel <input type="checkbox"/> e. Other:	
3. Wall Covering:	Clapboard <input checked="" type="checkbox"/> Board & Batten <input type="checkbox"/> Wood Shingle <input type="checkbox"/> Shiplap <input type="checkbox"/> Novelty <input type="checkbox"/> Asbestos Shingle <input type="checkbox"/> Sheet Metal <input type="checkbox"/> Aluminum <input type="checkbox"/> Asphalt Shingle <input type="checkbox"/> Brick Veneer <input type="checkbox"/> Stone Veneer <input type="checkbox"/> Bonding Pattern: Other:
4. Roof Structure	
a. Truss:	Wood <input checked="" type="checkbox"/> Iron <input type="checkbox"/> Steel <input type="checkbox"/> Concrete <input type="checkbox"/>
b. Other:	
5. Roof Covering:	Slate <input checked="" type="checkbox"/> Wood Shingle <input type="checkbox"/> Asphalt Shingle <input type="checkbox"/> Sheet Metal <input type="checkbox"/> Built Up <input type="checkbox"/> Rolled <input type="checkbox"/> Tile <input type="checkbox"/> Other:
6. Engineering Structure:	
7. Other:	
Appendages:	Porches <input checked="" type="checkbox"/> Towers <input type="checkbox"/> Cupolas <input type="checkbox"/> Dormers <input type="checkbox"/> Chimneys <input checked="" type="checkbox"/> Sheds <input type="checkbox"/> Ells <input type="checkbox"/> Wings <input type="checkbox"/> Bay Window <input type="checkbox"/> Other:
Roof Style:	Gable <input checked="" type="checkbox"/> Hip <input type="checkbox"/> Shed <input type="checkbox"/> Flat <input type="checkbox"/> Mansard <input type="checkbox"/> Gambrel <input type="checkbox"/> Jerkinhead <input type="checkbox"/> Saw Tooth <input type="checkbox"/> With Monitor <input type="checkbox"/> With Bellcast <input type="checkbox"/> With Parapet <input type="checkbox"/> With False Front <input type="checkbox"/> Other:
Number of Stories:	2½
Number of Bays:	2 x 2
Approximate Dimensions:	20' x 28'
Entrance Location:	Right bay gable front

SURVEY NUMBER:	1106-20
NEGATIVE FILE NUMBER:	82-A-124
UTM REFERENCES:	Zone/Easting/Northing 18 / 662375 / 4800750
U.S.G.S. QUAD. MAP:	Wallingford 15'
PRESENT FORMAL NAME:	
ORIGINAL FORMAL NAME:	
PRESENT USE:	Residence
ORIGINAL USE:	Residence
ARCHITECT/ENGINEER:	Unknown
BUILDER/CONTRACTOR:	Unknown
PHYSICAL CONDITION OF STRUCTURE:	Excellent <input type="checkbox"/> Good <input checked="" type="checkbox"/> Fair <input type="checkbox"/> Poor <input type="checkbox"/>
STYLE:	Vernacular
DATE BUILT:	c.1910

THREAT TO STRUCTURE:	LOCAL ATTITUDES:
No Threat <input checked="" type="checkbox"/> Zoning <input type="checkbox"/> Roads <input type="checkbox"/> Development <input type="checkbox"/> Deterioration <input type="checkbox"/> Alteration <input type="checkbox"/> Other:	Positive <input checked="" type="checkbox"/> Negative <input type="checkbox"/> Mixed <input type="checkbox"/> Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

Pedimented gable front form; first story porch spans front facade - it includes: pedimented gable roof, turned posts with unique scroll brackets that have a spindle decoration, entablature, wide eave, molded cornice, and balustrade. Main block has cornerboards, frieze board and deep eaves under a moderately heavy cornice. 1/1 sash with simple surrounds, oak door. 1½ story rear wing and shed roofed porch. Basement at grade in rear.

RELATED STRUCTURES: (Describe)

Detailed 1½ story clapboarded gabled barn. It includes two double swinging garage doors on west gable end and loft door above, a chimney, and 6/6 sash. It is detailed with cornerboards, beltcourse and a simple cornice which does not return. c.1910

STATEMENT OF SIGNIFICANCE:

The Danby Marble Industry experienced a revival during the early years of this century. The prosperity this brought caused the construction of several residences in and near the village; this structure included; Unaltered and well-preserved, it represents an evolution of the Greek Revival style common in Danby and Vermont.

REFERENCES:

MAP: (Indicate North in Circle)



DANBY VILLAGE

S. Main St.

1106-19

1106-20

1106-21

SURROUNDING ENVIRONMENT:

Open Land Woodland
 Scattered Buildings
 Moderately Built Up
 Densely Built Up
 Residential Commercial
 Agricultural Industrial
 Roadside Strip Development
 Other:

RECORDED BY:

Gina Campoli

ORGANIZATION:

Division for Historic Preservation

DATE RECORDED:

July 1982



82-A-124

Vt. Div. for Historic Preservation
Rutland Danby 7/82
Congregational Church Parsonage
1106-20
82-A-124 Gina Campoli

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

COUNTY: Rutland
TOWN: Danby
LOCATION: East side of S. Main Street,
just south of Danby Village and 1109-20.
COMMON NAME:
Congregational Church Parsonage
FUNCTIONAL TYPE: Residence
OWNER: Congregational Church
ADDRESS: Rev. Lester Tufts
Danby, VT 05739
ACCESSIBILITY TO PUBLIC:
Yes No Restricted
LEVEL OF SIGNIFICANCE:
Local State National

GENERAL DESCRIPTION:

Structural System
1. Foundation: Stone Brick Concrete Concrete Block
2. Wall Structure
a. Wood Frame: Post & Beam Balloon
b. Load Bearing Masonry: Brick Stone Concrete
Concrete Block
c. Iron d. Steel e. Other:
3. Wall Covering: Clapboard Board & Batten Wood Shingle
Shiplap Novelty Asbestos Shingle Sheet Metal
Aluminum Asphalt Shingle Brick Veneer Stone Veneer
Bonding Pattern: Other:
4. Roof Structure
a. Truss: Wood Iron Steel Concrete
b. Other:
5. Roof Covering: Slate Wood Shingle Asphalt Shingle
Sheet Metal Built Up Rolled Tile Other:
6. Engineering Structure:
7. Other:
Appendages: Porches Towers Cupolas Dormers Chimneys
Sheds Ells Wings Bay Window Other:
Roof Style: Gable Hip Shed Flat Mansard Gambrel
Jerkinhead Saw Tooth With Monitor With Bellcast
With Parapet With False Front Other:
Number of Stories: 2½
Number of Bays: 4 x 2 Entrance Location: Right center,
Approximate Dimensions: 28' x 20' eaves side

THREAT TO STRUCTURE:

No Threat Zoning Roads
Development Deterioration
Alteration Other:

SURVEY NUMBER:

1106-21

NEGATIVE FILE NUMBER:

82-A-124

UTM REFERENCES:

Zone/Easting/Northing

18 / 662475 / 4800700

U.S.G.S. QUAD. MAP:

Wallingford 15'

PRESENT FORMAL NAME:

Congregational Church Parsonage

ORIGINAL FORMAL NAME:

Congregational Church Parsonage

PRESENT USE: Parsonage

ORIGINAL USE: Parsonage

ARCHITECT/ENGINEER:

Unknown

BUILDER/CONTRACTOR:

Unknown

PHYSICAL CONDITION OF STRUCTURE:

Excellent Good
Fair Poor

STYLE: Vernacular Queen Anne

DATE BUILT:

1899

THREAT TO STRUCTURE:

LOCAL ATTITUDES:

Positive Negative
Mixed Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

Basic eave front form with gable roof. Shed roofed Queen Anne style porch spans the first floor front facade. It is decorated with a spindle valance and turned posts and balustrade. Main block includes corner boards, a thin frieze board and cornice without returns. 2/2 sash; slight lip molding above most of the windows, rear windows have cornice molding above 2 story gabled ell addition on rear facade with added 20th century hipped roof porch. Basement is at grade on rear facade.

RELATED STRUCTURES: (Describe)


1 1/2 story gabled clapboarded garage. Double garage door on gable ends; thin cornerboards and frieze boards. c.1910

STATEMENT OF SIGNIFICANCE:

The Church has maintained the parsonage in tip-top condition. The rear addition, according to the present resident, Rev. Tufts, includes recycled moldings, windows, etc. from earlier structures. The otherwise starkly plain house is enlivened by its contemporaneous Queen Anne style porch.

REFERENCES:

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

Open Land Woodland
Scattered Buildings
Moderately Built Up
Densely Built Up
Residential Commercial
Agricultural Industrial
Roadside Strip Development
Other:

RECORDED BY:

Gina Campoli

ORGANIZATION:

Division for Historic Preservation

DATE RECORDED:

July 1982



82-A-124

Vt. Div. for Historic Preservation
Rutland Danby 7/82
Congregational Church Parsonage
1106-21
82-A-124 Gina Campoli




NAME OF SITE	SITE NO.	NEGATIVE FILE NO.	N.R.
House	1106-30	89-A-93	
House	1106-31	89-A-93	
Long-Blinn Farm	1106-32	89-A-94, 83-A-392	
Bromley-Fernen Farm	1106-34	83-A-389 89-A-95	
Macheski House	1106-35	83-A-391 89-A-95	
House	1106-36	83-A-389 89-A-94	
Campbell-Billings House	1106-37	83-A-389 89-A-94	
Yrskha House	1106-38	89-A-94	
Warner-Kapuska House	1106-39	89-A-94	
Vermont Marble Co. Worker's Housing	1106-40	89-A-94	
Millard House	1106-41	83-A-388 89-A-92	
House	1106-42	83-A-388 89-A-92	
House	1106-43	83-A-392 89-A-92	
House	1106-45	83-A-388 89-A-92	
House	1106-46	83-A-388 89-A-92	
House	1106-47	83-A-388 89-A-173	
Rothman House	1106-48	89-A-95	
Neuman House	1106-49	89-A-95	
Feltz-Ihasz Barn	1106-50	89-A-95	
Lewis Barn	1106-51	89-A-95	
Fiske-Taconic Foundation	1106-52	83-A-392 89-A-95	
Hilliard House-Taconic Foundation	1106-53	83-A-389 89-A-95	
Herrick-Taconic Foundation	1106-54	89-A-95	
Coburn House	1106-55	83-A-389 89-A-93	
Danby Four Corners Store	1106-57	83-A-389 89-A-93	
Loomis Barn	1106-58	89-A-93	
Danby Town Hall	1106-59	83-A-389 89-A-93	
Gates House	1106-60	83-A-391 89-A-93	

NAME OF SITE	SITE NO.	NEGATIVE FILE NO.	N.R.
King House	1106-61	85-A-569 89-A-94	
[REDACTED]	[REDACTED]	[REDACTED]	

TOWN OF DANBY MAP

Sites Listed in the State Register of Historic Places
(Numbers correspond to Register listings that follow.)

For A see historic district map.)



STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

SURVEY NUMBER:
1106-22

NEGATIVE FILE NUMBER:
89 A 92:24 ; P3-A-39 #5

UTM REFERENCES:
Zone/Easting/Northing

18/652720/4805740

U.S.G.S. QUAD. MAP:
Middletown Springs, VT. 7.5'

PRESENT FORMAL NAME:

ORIGINAL FORMAL NAME:

PRESENT USE: vacant
ORIGINAL USE: schoolhouse
ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:
Excellent Good
Fair Poor

STYLE: vernacular

DATE BUILT:
c. 1915

COUNTY: Rutland
TOWN: Danby
LOCATION: West of TH-5, approx, 2.7 miles
north of junction with TH-1.

COMMON NAME:

PROPERTY TYPE: schoolhouse

OWNER:
ADDRESS:

ACCESSIBILITY TO PUBLIC:
Yes No Restricted

LEVEL OF SIGNIFICANCE:
Local State National

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone Brick Concrete Concrete Block

2. Wall Structure

a. Wood Frame: Post & Beam Balloon

b. Load Bearing Masonry: Brick Stone Concrete
Concrete Block

c. Iron d. Steel e. Other:

3. Wall Covering: Clapboard Board & Batten Wood Shingle
Shiplap Novelty Asbestos Shingle Sheet Metal
Aluminum Asphalt Siding Brick Veneer Stone Veneer

Bonding Pattern: Other:

4. Roof Structure

a. Truss: Wood Iron Steel Concrete

b. Other:

5. Roof Covering: Slate Wood Shingle Asphalt Shingle
Sheet Metal Built Up Rolled Tile Other:

6. Engineering Structure:

7. Other:

Appendages: Porches Towers Cupolas Dormers Chimneys
Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel
Jerkinhead Saw Tooth With Monitor With Bellcast

With Parapet With False Front Other:

Number of Stories: 1 1/2

Number of Bays: 3x2

Entrance Location: gable center

Approximate Dimensions: 10'x18'

SIGNIFICANCE: Architectural Historic Archeological

Historic Contexts:

Level of Significance:
Local State National

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

A 1½ story vernacular style gable roofed schoolhouse with small front entry porch. C. 1915. 10'x18'. Clapboard sheathing with simple corner boards, box cornice and rafter tails at eavelines. Vertical plank entry doors at gable center and left rear eave. Six 6/1 windows form characteristic bank of windows on left eave wall. Front entry is flanked by 6/1 sash. Entry porch has slate shed-roof with slight ornamental pediment, exposed rafter tails, and turned posts. Main block has red slate roof and interior brick chimney at ridgeline. Stone foundation.

RELATED STRUCTURES: (Describe)


STATEMENT OF SIGNIFICANCE:

This c. 1915 schoolhouse was built during the modest flurry of development preceding the Great Depression. It is a good example of a country schoolhouse, with noteworthy embellishments, particularly the Queen Anne style detailing of the entry porch, and the red slate roof.

REFERENCES:

The Historic Architecture of Rutland County
 Vermont Division Historic Preservation.

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Holly Hitchcock

ORGANIZATION:

Vt, Div. Historic Preservation

DATE RECORDED:

7/5/89



1106-22

89-92

24

Vt. Division for Historic Preservation
Rutland County Danby 7/89
Schoolhouse, 1106-22 W
89-A-92:24 Holly Hitchcock

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

COUNTY:	Rutland
TOWN:	Danby
LOCATION:	west of TH-4, approx.,.5miles north of junction with TH-13.
COMMON NAME:	Old Sherman Place
PROPERTY TYPE:	house
OWNER:	Lettie and Asil Ricketts
ADDRESS:	
ACCESSIBILITY TO PUBLIC:	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE:	Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone Brick Concrete Concrete Block
2. Wall Structure
 - a. Wood Frame: Post & Beam Balloon
 - b. Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - c. Iron d. Steel e. Other:
3. Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Siding Brick Veneer Stone Veneer
Bonding Pattern: Other:
4. Roof Structure
 - a. Truss: Wood Iron Steel Concrete
 - b. Other:
5. Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
6. Engineering Structure:
7. Other:

Appendages: Porches Towers Cupolas Dormers Chimneys
Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel
Jerkinhead Saw Tooth With Monitor With Bellcast
With Parapet With False Front Other:

Number of Stories: 1½ eave center
Number of Bays: 5x2 Entrance Location: cape cod
Approximate Dimensions: 26'x22'

SURVEY NUMBER:

1106-23

NEGATIVE FILE NUMBER:

89A93#11; 83A,392 #17

UTM REFERENCES:

Zone/Easting/Northing

18/657450/4806120

U.S.G.S. QUAD. MAP:

Middletown Springs, Vt. 7.5'

PRESENT FORMAL NAME:

ORIGINAL FORMAL NAME:

Edmund Kelly House

PRESENT USE: house

ORIGINAL USE: house

ARCHITECT/ENGINEER:

unknown

BUILDER/CONTRACTOR:

John Sherman

PHYSICAL CONDITION OF STRUCTURE:

Excellent Good

Fair Poor

STYLE: vernacular

DATE BUILT:

c.1830

SIGNIFICANCE: Architectural Historic Archeological

Historic Contexts:

Level of Significance:

Local State National

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

A 1½ story Vernacular style Cape Cod type residence. 5x2 bays. 26'x22'. Clapboard siding, molded cornice with returns, corner pilasters. Wide eave center entry has reeded surround and sidelights which are boarded over. Sash, with simple surrounds, are either 1/1 or 6/6. Small square windows at gable ends. Stone foundation, slate roof laid over wood shingles, central brick chimney. Exterior concrete block chimney at right eave front. Deteriorated condition.

RELATED STRUCTURES: (Describe)

A c1850 two story roofed horse barn with flushboard siding and slate roof. Double sliding vertical plank doors on front eave wall. Addition to the right has hinged vertical plank pass door on front eave wall. One story addition to the left has rolled shed roof and tarpaper over walls, pass door at front. Extremely deteriorated condition. Another barn has burned.


STATEMENT OF SIGNIFICANCE:

The present owner, the third generation to live here, remembers being told that this house was drawn to this spot by oxen c. 1860. The house possesses details characteristic of early Cape Cod types: the central chimney and gable-end windows. It is thought to have been built for Edmund Kelly, a second generation resident of the town.

REFERENCES:

personal interview Lettie Ricketts, owner 7/6/89
The Historic Architecture of Rutland County, Vermont Division Historic Preservation.

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Holly Hitchcock

ORGANIZATION:

Vt Div Historic Preservation

DATE RECORDED:

7/7/89



1106-23

89-93

Vt. Division for Historic Preservation

Rutland County Danby 7/89

Ricketts House, 1106-23 NW

89-A-93:11 Holly Hitchcock

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

COUNTY:	Rutland
TOWN:	Danby
LOCATION:	east of TH-4, approx. .3 miles north of junction with TH-13.
COMMON NAME:	
PROPERTY TYPE:	house
OWNER:	Richard Kievit, Jr.
ADDRESS:	
ACCESSIBILITY TO PUBLIC:	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE:	Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone Brick Concrete Concrete Block
2. Wall Structure
 - a. Wood Frame: Post & Beam Balloon
 - b. Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - c. Iron d. Steel e. Other:
3. Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Siding Brick Veneer Stone Veneer
Bonding Pattern: Other:
4. Roof Structure
 - a. Truss: Wood Iron Steel Concrete
 - b. Other:
5. Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
6. Engineering Structure:
7. Other:

Appendages: Porches Towers Cupolas Dormers Chimneys
Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel
Jerkinhead Saw Tooth With Monitor With Bellcast
With Parapet With False Front Other:

Number of Stories: 1½

Number of Bays: 5x2

Entrance Location: classic cottage

Approximate Dimensions: 20'x14'

SIGNIFICANCE: Architectural Historic Archeological

Historic Contexts:

Level of Significance:
Local State National

SURVEY NUMBER:

1106-24

NEGATIVE FILE NUMBER:

89A93:12; 83A392:16

UTM REFERENCES:

Zone/Easting/Northing

18/657590/4805810

U.S.G.S. QUAD. MAP:

Middletown Springs, Vt. 7.5'

PRESENT FORMAL NAME:

ORIGINAL FORMAL NAME:

PRESENT USE: house

ORIGINAL USE: house

ARCHITECT/ENGINEER:

unknown

BUILDER/CONTRACTOR:

Ransom Kelly

PHYSICAL CONDITION OF STRUCTURE:

Excellent Good

Fair Poor

STYLE: Greek Revival

DATE BUILT:

c. 1850

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

A 1½ story Greek Revival style Classic Cottage with new one story ell. 5x2 bays. 20'x14'. Clapboard siding, corner pilasters, molded cornice with returns, wide frieze board. Eave center entry has full entablature, 3/4 four light sidelights, and marble steps. Evenly spaced 6/6 sash throughout. Concrete faced stone foundation, slate roof, exterior brick chimneys on left gable of main block, and rear gable of ell. Gable roofed ell has clapboard siding and slate roof; 24 light picture window on rear eave wall, entry on rear gable wall.

RELATED STRUCTURES: (Describe)


c 1880, A. A two story shed/garage, formerly a horse barn. Vertical plank siding, corrugated metal gable roof. Eastern eave wall has centered sliding vertical plank door, flanked by fixed six light sash; western eave wall has new centered overhead door, beneath hinged haydoor. Stone found-

STATEMENT OF SIGNIFICANCE:

This is an excellent example of an early Classic Cottage type residence with Greek Revival style influence. Inscriptions found in the remaining barn date the construction of the house as 1856, and it is locally believed that the first owners lived in the barn until construction was completed.

REFERENCES:

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Holly Hitchcock

ORGANIZATION:

Vt Div. Historic Preservation

DATE RECORDED:

7/7/89

RELATED STRUCTURES CONTINUED:

ation. Originally one of three related barns, the other two have collapsed.

B. A c1930 one story gable roofed milkhouse with clapboard siding and slate roof, converted to a sugarhouse by the present owner.



1106-24

Vt. Division for Historic Preservation
Rutland County Danby 7/89
Kievit House, 1106-24 SE
89-A-93:12 Holly Hitchcock

89-93

12

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

COUNTY:	Rutland
TOWN:	Danby
LOCATION:	east of Th-2, approx. .1 mile south of Baker Brook.
COMMON NAME:	
PROPERTY TYPE:	house
OWNER:	
ADDRESS:	
ACCESSIBILITY TO PUBLIC:	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE:	Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone Brick Concrete Concrete Block
2. Wall Structure
 - a. Wood Frame: Post & Beam Balloon
 - b. Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - c. Iron d. Steel e. Other:
3. Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Siding Brick Veneer Stone Veneer Bonding Pattern: Other:
4. Roof Structure
 - a. Truss: Wood Iron Steel Concrete
 - b. Other:
5. Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
6. Engineering Structure:
7. Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 2

Number of Bays: 5x2 Entrance Location: I-house

Approximate Dimensions: 30'x14'

SURVEY NUMBER: 1106-25
NEGATIVE FILE NUMBER: 89A93:9,10, 83A392:13,14,15
UTM REFERENCES: Zone/Easting/Northing 18/658300/4805070
U.S.G.S. QUAD. MAP: Middletown Springs, Vt. 7.5'
PRESENT FORMAL NAME:
ORIGINAL FORMAL NAME:
PRESENT USE: house
ORIGINAL USE: house
ARCHITECT/ENGINEER: unknown
BUILDER/CONTRACTOR: Asa Smith
PHYSICAL CONDITION OF STRUCTURE: Excellent <input type="checkbox"/> Good <input checked="" type="checkbox"/> Fair <input type="checkbox"/> Poor <input type="checkbox"/>
STYLE: Federal
DATE BUILT: c.1820

SIGNIFICANCE: Architectural <input checked="" type="checkbox"/> Historic <input type="checkbox"/> Archeological <input type="checkbox"/>	
Historic Contexts:	Level of Significance: Local State National

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

A two story Federal style I-house, with successive rear ells. Clapboard siding, corner pilasters, molded cornice with returns, and wide freize board. Eave center entry has full entablature with dentil work, entry pilasters, 3/4 sidelights, and semielliptical fanlight. Evenly spaced 12/12 sash. Slate-roofed porch at right of two story ell has square posts and slate floor; it fronts secondary entry. 6/6 sash in wll. One story gable roofed breezeway connects ell to gable roofed garage with two overhead doors facing south.

RELATED STRUCTURES: (Describe)

A c. 1925 2½ story level stable barn with gambrel roof. 48'x18'. Clapboard siding, corrugated metal roof with hoist at northern gable end. Sliding vertical plank barn doors flanked by fixed six light sash on both gable walls hinged haydoor in northern gable peak. Evenly spaced sash on both eave walls;


STATEMENT OF SIGNIFICANCE

This c. 1820 Greek Revival style I-house was built for Asa Smith, a second generation resident of the town. The house has a particularly attractive enriched entryway and a handsome related ground level stable barn.

REFERENCES:

The Historic Architecture of Rutland County
Vermont Division Historic Preservation

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Holly Hitchcock

ORGANIZATION:

Vt Div Historic Preservation

DATE RECORDED:

7/7/89

RELATED STRUCTURES CONTINUED:

pass doors at center and far right of western eave wall. Concrete coping reinforces original stone foundation.



1106-25

89-93
Vt. Division for Historic Preservation

Rutland County Danby 7/89

Smith House, 1106-25 NE

89-A-93:9 Holly Hitchcock

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

COUNTY:	Rutland
TOWN:	Danby
LOCATION:	east of TH-15, approx, 1.3 miles north of junction with TH-20.
COMMON NAME:	
PROPERTY TYPE:	barn
OWNER:	Croce
ADDRESS:	
ACCESSIBILITY TO PUBLIC:	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE:	Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone Brick Concrete Concrete Block
 2. Wall Structure
 - a. Wood Frame: Post & Beam Balloon
 - b. Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - c. Iron d. Steel e. Other:
 3. Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Siding Brick Veneer Stone Veneer
Bonding Pattern: Other:
 4. Roof Structure
 - a. Truss: Wood Iron Steel Concrete
 - b. Other:
 5. Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
 6. Engineering Structure:
 7. Other:
- Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:
- Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:
- Number of Stories: 1½
- Number of Bays: 3x8 Entrance Location: gable center
- Approximate Dimensions: 30'x60'

SIGNIFICANCE: Architectural Historic Archeological

Historic Contexts:

SURVEY NUMBER:

1106-27

NEGATIVE FILE NUMBER:

89 A 93:8 83-A-392 #19

UTM REFERENCES:

Zone/Easting/Northing

18/659680/4804480

U.S.G.S. QUAD. MAP:

Middletown Springs, Vt. 7.5'

PRESENT FORMAL NAME:

ORIGINAL FORMAL NAME:

PRESENT USE: house

ORIGINAL USE: camp

ARCHITECT/ENGINEER:

unknown

BUILDER/CONTRACTOR:

unknown

PHYSICAL CONDITION OF STRUCTURE:

Excellent Good

Fair Poor

STYLE: vernacular

DATE BUILT:

c. 1880

Level of Significance:

Local State National

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:


A 1½ story bank barn with gable front main level facing road. 3x8 bays. 30'x60'. Small wing, formerly the milkhouse, is now a summer residence. Clapboard siding, corner boards, simple box cornice. Gable front has sliding vertical plank door, beneath an transom window. Flanking windows are boarded over. Eave walls have irregularly spaced windows; most lack sash. Stone foundation, slate roof. Milkhouse wing near front left has novelty siding and slate roof, new sash.

RELATED STRUCTURES: (Describe)

STATEMENT OF SIGNIFICANCE:

This c. 1880 bank barn is large and well constructed. It was built during a period of expansion to accomodate larger dairy herds. Despite its conversion to a summer residence, it is essentially unchanged.

REFERENCES:



- SURROUNDING ENVIRONMENT:**
- Open Land Woodland
 - Scattered Buildings
 - Moderately Built Up
 - Densely Built Up
 - Residential Commercial
 - Agricultural Industrial
 - Roadside Strip Development
 - Other:

RECORDED BY:
Holly Hitchcock

ORGANIZATION:
Vt Div Historic Preservation

DATE RECORDED:
7/7/89



1106-27

Vt. Division for Historic Preservation
Rutland County Danby 7/89
Croce Barn, 1106-27 NE
89-A-93:8 Holly Hitchcock

89-93

8

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

SURVEY NUMBER: 1106-28
NEGATIVE FILE NUMBER: 89A93:4,5,67 83A 391-16,17
UTM REFERENCES: Zone/Easting/Northing 18/660350/4802350
U.S.G.S. QUAD. MAP: Dorset, Vt. 7.5'
PRESENT FORMAL NAME: Staples Farm
ORIGINAL FORMAL NAME:
PRESENT USE: farm
ORIGINAL USE: farm
ARCHITECT/ENGINEER: unknown
BUILDER/CONTRACTOR: unknown
PHYSICAL CONDITION OF STRUCTURE: Excellent <input type="checkbox"/> Good <input checked="" type="checkbox"/> Fair <input type="checkbox"/> Poor <input type="checkbox"/>
STYLE: vernacular
DATE BUILT: c.1900

COUNTY: Rutland
TOWN: Danby
LOCATION: east of TH-20, approx, .6 miles south of junction with TH-21.
COMMON NAME:
PROPERTY TYPE: farm
OWNER: Edwin Staples
ADDRESS:
ACCESSIBILITY TO PUBLIC: Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE: Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone Brick Concrete Concrete Block
2. Wall Structure
 - a. Wood Frame: Post & Beam Balloon
 - b. Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - c. Iron d. Steel e. Other:
3. Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Siding Brick Veneer Stone Veneer Bonding Pattern: Other:
4. Roof Structure
 - a. Truss: Wood Iron Steel Concrete
 - b. Other:
5. Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
6. Engineering Structure:
7. Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 1 1/2

Number of Bays: 5x2 Entrance Location: classic cottage

Approximate Dimensions: 30'x20'

SIGNIFICANCE: Architectural <input checked="" type="checkbox"/> Historic <input type="checkbox"/> Archeological <input type="checkbox"/>
Historic Contexts:
Level of Significance: Local State National

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

A 1½ story vernacular style Classic Cottage type farmhouse with southern wing and unusual dormer. 5x2 bays. Primarily clapboarded, however, southern and rear walls of wing are aluminum sided. Box cornice, simple corner and water table boards. 2/2 sash with simple surrounds, various new sash in wing. Centered gable dormer on main block protrudes over open Queen Anne style porch with scrollsawn brackets and straight posts. Queen Anne style porch fronting wing has scrollsawn brackets, chamfered posts, corrugated metal roof. Porch on rear of main block is now gone. Stone and marble foundation, slate gable roof, interior brick chimneys at both ends of main block ridgeline and centered on wing. Marble walk to road.

RELATED STRUCTURES: (Describe)


A. A c.1900 1½ story vernacular style carriage barn with clapboard siding and slate gable roof. Eave front entries have double leaf sliding vertical plank doors to the left., double leaf sliding doors with applied wooden ornamentation to the right. It appears that the original structure was comprised only of the left half; later, joined with the right half. Slate, hip roofed

STATEMENT OF SIGNIFICANCE:

The Staples Farm, with its c.1900 farmhouse, and various outbuildings, is a good example of a turn of the century Danby hill farm. It commands a remarkably beautiful hillside site, and may be endangered by the sheer desirability of the location. The Classic Cottage typw house has an unusual gable dormer and attractive porches.

REFERENCES:

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Holly Hitchcock

ORGANIZATION:

Vt Div Historic Preservation

DATE RECORDED:

10/11/89

RELATED STRUCTURES CONTINUED:

cupola centered on right half. Centered vertical plank pass door, flanked by, and below eight light sash, is on eastern gable wall. Small shed roofed addition with rolled roof and clapboard siding is on western gable wall.

B. A c1900 1½ story vernacular style ground level stable barn with novelty siding and corrugated metal roof. 26'x40'. Gable center entry is flanked by six light sash, with hinge haydoor, flanked by empty sash, in gable peak. Hoist above. Two southern gable roofed wings are connected by shed roofed addition with corrugated metal roof. Raised concrete foundation, encircling building, forms large portion of addition walls. Northern shed roofed milkhouse addition has corrugated metal roof, aluminum siding, vertical plank pass door and two six light windows. Free standing metal silo at rear of structure.

C. A c1900 barn comprised of several joined buildings. Gable front, with successive additions. Primarily clapboard; rear addition is of vertical plank. Main block (farthest front) has slate gable roof, eave left, open, entry. Rubblestone foundation.



1106-28

Vt. Division for Historic Preservation
Rutland County Danby 7/89
Staples House, 1106-28 SE
89-A-93:4 Holly Hitchcock

89-93

4



1106-28

89-93

7

Vt. Division for Historic Preservation
Rutland County Danby 7/89
Staples Barns, 1106-28 SE
89-A-93:7 Holly Hitchcock

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

SURVEY NUMBER:

1106-29

NEGATIVE FILE NUMBER:

89A93:3 83A392: 6,7

UTM REFERENCES:

Zone/Easting/Northing

18/661150/4803910

U.S.G.S. QUAD. MAP:

Dorset, Vt. 7.5'

PRESENT FORMAL NAME:

ORIGINAL FORMAL NAME:

PRESENT USE: house

ORIGINAL USE: house

ARCHITECT/ENGINEER:

unknown

BUILDER/CONTRACTOR:

unknown

PHYSICAL CONDITION OF STRUCTURE:

Excellent Good

Fair Poor

STYLE: Greek Revival

DATE BUILT:

c. 1895

COUNTY: Rutland

TOWN: Danby

LOCATION: west of TH-20, at junction
with TH-21.

COMMON NAME:

PROPERTY TYPE: house

OWNER:

ADDRESS:

ACCESSIBILITY TO PUBLIC:

Yes No Restricted

LEVEL OF SIGNIFICANCE:

Local State National

GENERAL DESCRIPTION:

Structural System

- 1. Foundation: Stone Brick Concrete Concrete Block
- 2. Wall Structure
 - a. Wood Frame: Post & Beam Balloon
 - b. Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - c. Iron d. Steel e. Other:
- 3. Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Siding Brick Veneer Stone Veneer Bonding Pattern: Other:
- 4. Roof Structure
 - a. Truss: Wood Iron Steel Concrete
 - b. Other:
- 5. Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
- 6. Engineering Structure:
- 7. Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 1½

Number of Bays: 5x2

Entrance Location: classic cottage

Approximate Dimensions: 24'x16'

SIGNIFICANCE: Architectural Historic Archeological

Historic Contexts:

Level of Significance:
Local State National

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

A 1½ story Greek Revival style Classic Cottage, with two successive wings. 5x2 bays. 24'x16'. Clapboard siding, molded cornice with returns, panelled corner pilasters. Kneewall windows set in wide freizeboard have distinctive ornamentation. 6/6 sash. Wide eave center entry has full entablature and panelled pilasters. Doorway is presently boarded over; further details are obscured. concrete faced marble foundation, with cellar entance on northern gable wall. Slate roof, wxterior brick chimney faced with limestone at rear right. First southern wing has slate gable roof, clapboard siding, and slate shedroofed porch with square posts fronting eave right entry. Panelled corner pilasters repeat those of main block. Second southern wing is smaller with slate gable roof, clapboard siding and central front entry flanked by double 3/3 windows. Semicircular marble steps lead to main block entry.

RELATED STRUCTURES: (Describe)


- A. c1880 shed, gable roof, clapboard siding, very deteriorated.
- B. c1980 gabled barn Non- contributing due to age.

STATEMENT OF SIGNIFICANCE:

This c. 1855 structure is a good example of a Greek Revival style Classic Cottage. Particularly noteworthy are the ornamental kneewall windows and entryway with full entablature. Marble is used extensively in the foundation and front steps.

REFERENCES:

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Holly Hitchcock

ORGANIZATION:

Vt Div Historic Preservation

DATE RECORDED:

7/7/89



1106-29

89-93
Vt. Division for Historic Preservation
Rutland County Danby 7/89
House, 1106-29 W
89-A-93:3 Holly Hitchcock

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

SURVEY NUMBER: 1106- 30
NEGATIVE FILE NUMBER: 89 A 93:2
UTM REFERENCES: Zone/Easting/Northing 18/661240/4804460
U.S.G.S. QUAD. MAP: Middletown Springs, Vt. 7.5'
PRESENT FORMAL NAME:
ORIGINAL FORMAL NAME: Benjamin Kelly House
PRESENT USE: house
ORIGINAL USE: house
ARCHITECT/ENGINEER: unknown
BUILDER/CONTRACTOR: unknown
PHYSICAL CONDITION OF STRUCTURE: Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor <input type="checkbox"/>
STYLE: Vernacular
DATE BUILT: c. 1790

COUNTY: Rutland
TOWN: Danby
LOCATION: east of TH-20, approx. .5mils. south of right angle turn to Scottsville
COMMON NAME:
PROPERTY TYPE: house
OWNER:
ADDRESS:
ACCESSIBILITY TO PUBLIC: Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE: Local <input checked="" type="checkbox"/> State <input type="checkbox"/> National <input type="checkbox"/>

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone Brick Concrete Concrete Block
2. Wall Structure
 - a. Wood Frame: Post & Beam Balloon
 - b. Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - c. Iron d. Steel e. Other:
3. Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Siding Brick Veneer Stone Veneer Bonding Pattern: Other:
4. Roof Structure
 - a. Truss: Wood Iron Steel Concrete
 - b. Other:
5. Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
6. Engineering Structure:
7. Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 1½

Number of Bays: 4x2

Approximate Dimensions: 26'x20'

Entrance Location: cape cod

SIGNIFICANCE: Architectural <input type="checkbox"/> Historic <input checked="" type="checkbox"/> Archeological <input type="checkbox"/>
Historic Contexts:
Level of Significance: Local State National

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

A 1½ story c. 1790 Cape Cod type house with new two story garage wing to the left. 4x2 bays. 26'x20'. Clapboard siding, narrow corner boards, slight eave overhang. Center entry with two 9/6 windows to the left, one to the right. No kneewall area over sash. New concrete block foundation has replaced rubblestone. Entrance to cellar at rear is through original stone foundation. Broad gable roof has new asphalt shingles, massive central brick chimney. New garage wing is clapboarded with asphalt shingle gable roof, clear kneewall windows over french doors at eave ends. New open decks with straight balustrades run across second story level of wing and ground level of main block. Large block of marble serves as threshold at front main entrance.

RELATED STRUCTURES: (Describe)


STATEMENT OF SIGNIFICANCE:

This rare c. 1790 structure may well have been one of the first houses built in Danby. It retains the characteristics of an early Cape Cod type, despite modernization. It was the homestead of Benjamin Kelly from Rhode Island, one of Danby's earliest settlers.

REFERENCES:

The Historic Architecture of Rutland County
Vermont Division Historic Preservation

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Holly Hitchcock

ORGANIZATION:

Vt Div. Historic Preservation

DATE RECORDED:

7/7/89



1106-30

Vt. Division for Historic Preservation
Rutland County Danby 7/89
Kelly House, 1106-30 E
89-A-93:2 Holly Hitchcock

89-93

2

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

SURVEY NUMBER:

1106-31

NEGATIVE FILE NUMBER:

89 A 93:0,1

UTM REFERENCES:

Zone/Easting/Northing

18/661320/4805200

U.S.G.S. QUAD, MAP:

Middletown Springs, Vt. 7.5'

PRESENT FORMAL NAME:

ORIGINAL FORMAL NAME:

PRESENT USE: house

ORIGINAL USE: house

ARCHITECT/ENGINEER:

unknown

BUILDER/CONTRACTOR:

unknown

PHYSICAL CONDITION OF STRUCTURE:

Excellent Good

Fair Poor

STYLE: vernacular

DATE BUILT:

c1810

COUNTY: Rutland
 TOWN: Danby
 LOCATION: end of TH-37, approx, .1 mile north of junction with TH-20.
 COMMON NAME:
 PROPERTY TYPE: house
 OWNER:
 ADDRESS:
 ACCESSIBILITY TO PUBLIC:
 Yes No Restricted
 LEVEL OF SIGNIFICANCE:
 Local State National

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone Brick Concrete Concrete Block
2. Wall Structure
 - a. Wood Frame: Post & Beam Balloon
 - b. Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - c. Iron d. Steel e. Other:
3. Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Siding Brick Veneer Stone Veneer Bonding Pattern: Other:
4. Roof Structure
 - a. Truss: Wood Iron Steel Concrete
 - b. Other:
5. Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
6. Engineering Structure:
7. Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 1 1/2

Number of Bays: 5x2

Entrance Location: cape cod

Approximate Dimensions: 24'x20'

SIGNIFICANCE: Architectural Historic Archeological

Historic Contexts:

Level of Significance:

Local State National

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

A 1½ story vernacular style Cape Cod type residence with new one story gable roofed wing. 24'x20'. Aluminum siding has replaced or obscured some details. Simple corner boards. New window surrounds. Regularly spaced 6/6 sash; paired flanking eave central entry. Entry has modest entablature, reeded pilasters, and 3/4 three-light sidelights, marble steps. Stone foundation, slate roof, central brick chimneys on main block and wing. Wing has irregularly placed sash; some four-part, some two, horizontal sash at kneewall, and entries at front and rear of eave walls.

RELATED STRUCTURES: (Describe)

A. c1890 very large, 35'x55', 2½ story tri-gabled ell bank barn is joined to separate gable roofed barn structure, with various shed additions. Main block has clapboard siding, corner boards, slate roof. Gable front wall has three ground level evenly spaced windows with peaked lintels over lower level cattle drive entry; windows in all three gable peaks, and irregularly


STATEMENT OF SIGNIFICANCE:

This c. 1810 structure is one of many early Cape Cod type residences in the Scottsville section of Danby. Despite the addition of a new wing and siding, it retains many distinctive features. The large early bank barn and surrounding agricultural land maintain the atmosphere of an early hill farm.

REFERENCES:

The Historic Architecture of Rutland County
Vermont Division Historic Preservation

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Holly Hitchcock

ORGANIZATION:

Vt Div. Historic Preservation

DATE RECORDED:

7/7/89

RELATED STRUCTURES CONTINUED:

AT GROUND LEVEL. All sash are missing. Full height sliding vertical plank door on northern eave wall. Rubblestone foundation. Wing has flushboard siding, corner boards, a deteriorated slate roof, and concrete foundation. Sliding clapboard entry door at gable left, with three small windows, lacking sash, to the right. Haydoor above. Two successive, shed roofed additions, formerly the milkhouse area, have clapboard siding, a corrugated metal roof and irregularly spaced windows.

B. A c1890 2½ story gable roofed carriage barn, which is no longer contributing due to substantial alteration. Aluminum siding, slate roof, concrete block foundation. Three eave front bays have overhead garage doors.



1106-31

89-93

#1

Vt. Division for Historic Preservation
Rutland County Danby 7/89
House, 1106-31 NE
89-A-93:1 Holly Hitchcock



1106-31

89-93

0

Vt. Division for Historic Preservation
Rutland County Danby 7/89
Barn, 1106-31 N
89-A-93:0 Holly Hitchcock

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

SURVEY NUMBER: 1106-31
NEGATIVE FILE NUMBER: 89 A 94:5,6,7,8,9 P3-A-392#2.1
UTM REFERENCES: Zone/Easting/Northing 18/662015/4802095
U.S.G.S. QUAD. MAP: Wallingford Vt. 15'
PRESENT FORMAL NAME:
ORIGINAL FORMAL NAME:
PRESENT USE: barn
ORIGINAL USE: barn
ARCHITECT/ENGINEER: unknown
BUILDER/CONTRACTOR: unknown
PHYSICAL CONDITION OF STRUCTURE: Excellent <input type="checkbox"/> Good <input checked="" type="checkbox"/> Fair <input type="checkbox"/> Poor <input type="checkbox"/>
STYLE: vernacular
DATE BUILT: c.1910

COUNTY: Rutland
TOWN: Danby
LOCATION: east of TH-19, approx, .4miles south of junction with TH-21.
COMMON NAME: Anna Long Farm
PROPERTY TYPE: barn
OWNER: Barney Blinn
ADDRESS:
ACCESSIBILITY TO PUBLIC: Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE: Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone Brick Concrete Concrete Block
2. Wall Structure
 - a. Wood Frame: Post & Beam Balloon
 - b. Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - c. Iron d. Steel e. Other:
3. Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Siding Brick Veneer Stone Veneer Bonding Pattern: Other:
4. Roof Structure
 - a. Truss: Wood Iron Steel Concrete
 - b. Other:
5. Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
6. Engineering Structure:
7. Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 1 1/2

Number of Bays: 1x2 Entrance Location: eave center

Approximate Dimensions: 40'x30'

SIGNIFICANCE: Architectural <input checked="" type="checkbox"/> Historic <input type="checkbox"/> Archeological <input type="checkbox"/>
Historic Contexts:
Level of Significance: Local State National

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

A 1½ story gambrel roofed Vernacular style bank barn, with eavefront high-drive, is boarded over. Three basement level windows with six light sash, flank high drive at lower level. Double leaf vertical plank doors are centered on both gable walls, at basement level. Small boarded over sash in both gable peaks. Cupolas are louvered, with slate hip roofs. Stone foundation with concrete foundation of formerly standing milkhouse to right of high-drive.

RELATED STRUCTURES: (Describe)

A. A c1835 1½ story vernacular style Classic Cottage type residence, with rear wing with open side porch. Clapboard siding, molded cornice with returns and wide freize board, corner boards. 5x2 bays. 24'x20'. Eave central entry has full entablature, and entry pilasters. Window size has been altered and new 1/1 sash is used throughout. Kneewall windows are now


STATEMENT OF SIGNIFICANCE:

This c. 1910 bank barn was doubtless added to accomodate larger dairy herds during a period of relative agricultural prosperity. It is later than the c. 1835 Classic Cottage type residence with which it is associated, and is one of many prosperous farms along the former stage-coach route into Danby Borough.

REFERENCES:

Personal interview with Paul Pierce, life-long resident. The Historic Architecture of Rutland County, V.D.H.P

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Holly Hitchcock

ORGANIZATION:

Vt Div Historic Preservation

DATE RECORDED:

7/13/89

RELATED STRUCTURES CONTINUED:

clear, top-hinged, casements. Stone foundation, slate roof, corbelled brick Colonial Revival style chimney on southern gable wall. 1½ story wing is clapboarded, with slate roof and central brick chimney. Wing entry is through open side porch with square posts.

B. c1900 1½ story vernacular style gable roofed barn with one story wing. Clapboard siding, and asphalt shingle roof. Substantially altered fenestration, and door placement. Building is now used as garage and rental unit. (s). Non-contributing due to alteration.



1106-32

89-94

7

Vt. Division for Historic Preservation
Rutland County Danby 7/89
Long Barn, 1106-32 SE
89-A-94:7 Holly Hitchcock



1106-32

89-94
5

Vt. Division for Historic Preservation
Rutland County Danby 7/89
Long House, 1106-32 E
89-A-94:5 Holly Hitchcock

STATE OF VERMONT
 Division for Historic Preservation
 Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
 Individual Structure Survey Form

COUNTY:	Rutland
TOWN:	Danby
LOCATION:	north of TH-27, approx, .7 miles north of Danby center.
COMMON NAME:	Bromley Farm
PROPERTY TYPE:	house
OWNER:	Eugene Fernen
ADDRESS:	
ACCESSIBILITY TO PUBLIC:	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE:	Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>

GENERAL DESCRIPTION:

Structural System

- Foundation: Stone Brick Concrete Concrete Block
- Wall Structure
 - Wood Frame: Post & Beam Balloon
 - Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - Iron d. Steel e. Other:
- Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Siding Brick Veneer Stone Veneer Bonding Pattern: Other:
- Roof Structure
 - Truss: Wood Iron Steel Concrete
 - Other:
- Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
- Engineering Structure:
- Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 2½

Number of Bays: 5x2

Approximate Dimensions: 30'x18'

Entrance Location: Georgian Plan

SURVEY NUMBER:	1106-34
NEGATIVE FILE NUMBER:	89A95:19,20,21; 83 A 389:20,21
UTM REFERENCES:	Zone/Easting/Northing
	18/662015/4802080
U.S.G.S. QUAD. MAP:	Wallingford, Vt. 15'
PRESENT FORMAL NAME:	
ORIGINAL FORMAL NAME:	
PRESENT USE:	house
ORIGINAL USE:	farm
ARCHITECT/ENGINEER:	unknown
BUILDER/CONTRACTOR:	Bromley
PHYSICAL CONDITION OF STRUCTURE:	Excellent <input type="checkbox"/> Good <input checked="" type="checkbox"/> Fair <input type="checkbox"/> Poor <input type="checkbox"/>
STYLE:	vernacular
DATE BUILT:	c. 1865

SIGNIFICANCE:	Architectural <input checked="" type="checkbox"/> Historic <input checked="" type="checkbox"/> Archeological <input type="checkbox"/>
Historic Contexts:	Level of Significance: Local State National

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

A 2½ story Georgian Plan Vernacular style residence with rear gable extension, wing, ell, and wraparound porch. 5x2 bays. 30'x18'. Aluminum siding, molded cornice with returns, simple window surrounds. Paired 1/1 sash flanks wide eave central entrance with 1/2 sidelights and boarded over fanlight. 1/1 sash with new shutters throughout. Wraparound Italianate style open porch has hip slate roof, decorative brackets and modillion blocks, straight columns with bases, and lattice skirt. Brackets and modillion blocks are repeated on three sided bay window on northern gable wall. Entry at center of southern gable wall has wide surround. Rear gable extension at rear left intersects with one story gable roofed wing at rear right. Small shed roofed wall with asphalt shingle roof extends from the wing to the right. One 9/6 window remains in ell. New brick patio fronts main block/ell intersection. Stone foundation, slate roof, new central brick chimney constructed by local mason to duplicate lines of original which it replaces.

RELATED STRUCTURES: (Describe)

A. A 1½ story gable roofed carriage barn with adjoining new dairy barn ell.
 C. 1895. Narrow clapboard siding, corner boards, slate roof. Gable peak areas are of imbricated shingles with one 6/6 window, with slate hood and carved decorative brackets. Stone foundation. Carriage bay entry now forms junction with new dairy barn ell. Ell has clapboard siding, corrugated metal


STATEMENT OF SIGNIFICANCE:

It is locally remembered that this 600 acre farm, owned by the Bromley family, was the exemplar of a prosperous Danby hill farm and that, when the Bromleys harnessed up and drove down into the borough, it was an impressive and envied sight. The house is a good example of a comfortable c. 1865 farmhouse, and many of the original barns and outbuildings still stand.

REFERENCES:

personal interview Eugene Fernen, Owner 7/19/89

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Holly Hitchcock

ORGANIZATION:

Vt Div. Historic Preservation

DATE RECORDED:

7/19/89

RELATED STRUCTURES CONTINUED:

gable roof, gable front sliding vertical plank barn doors. Haydoor above. One story corrugated metal gable roofed milkhouse addition with vertical plank front door pass door at right. High concrete foundation.

B. C. 1865. A 1½ story gable roofed barn; one of two original barns still standing. 20'x14'. Vertical flushboard siding, slate roof. Irregularly spaced boarded over sash. Eave central sliding vertical plank barn doors on both eave walls. Hinged vertical plank hay doors in both gable peaks. Rubblestone foundation.

C. C. 1865. A smaller 1½ story gable roofed barn with vertical flushboard siding and slate roof. 14'x12'. Sliding vertical plank barn door on eave front wall, vertical plank pass door at right rear. Haydoor in northern gable peak, over two, spaced six light windows. Stone foundation.



1106-34

Vt. Division for Historic Preservation
Rutland County Danby 7/89
Fernen House, 1106-34 W
89-A-95:19 Holly Hitchcock

89-95

19



1106-34

89-95

20

Vt. Division for Historic Preservation
Rutland County Danby 7/89
Fernen Barn, 1106-34 W
89-A-95:20 Holly Hitchcock

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

SURVEY NUMBER: 1106-35
NEGATIVE FILE NUMBER: 89A95: 17,18; 83A391:9
UTM REFERENCES: Zone/Easting/Northing 18/662020/4802030
U.S.G.S. QUAD. MAP: Wallingford, Vt. 15'
PRESENT FORMAL NAME:
ORIGINAL FORMAL NAME:
PRESENT USE: house
ORIGINAL USE: tenant house
ARCHITECT/ENGINEER: unknown
BUILDER/CONTRACTOR: Delmar Gorton
PHYSICAL CONDITION OF STRUCTURE: Excellent <input type="checkbox"/> Good <input checked="" type="checkbox"/> Fair <input type="checkbox"/> Poor <input type="checkbox"/>
STYLE: vernacular
DATE BUILT: c 1900

COUNTY: Rutland
TOWN: Danby
LOCATION: west of TH-27, approx, .6miles north of center of Danby Village.
COMMON NAME:
PROPERTY TYPE: house
OWNER: Helen Macheski
ADDRESS:
ACCESSIBILITY TO PUBLIC: Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE: Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone Brick Concrete Concrete Block
2. Wall Structure
 - a. Wood Frame: Post & Beam Balloon
 - b. Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - c. Iron d. Steel e. Other:
3. Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Siding Brick Veneer Stone Veneer Bonding Pattern: Other:
4. Roof Structure
 - a. Truss: Wood Iron Steel Concrete
 - b. Other:
5. Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
6. Engineering Structure:
7. Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 2 1/2

Number of Bays: 5x2 Entrance Location: Georgian Plan

Approximate Dimensions: 24'x16'

SIGNIFICANCE: Architectural <input checked="" type="checkbox"/> Historic <input type="checkbox"/> Archeological <input type="checkbox"/>
Historic Contexts:
Level of Significance: Local State National

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

A 2½ story Georgian Plan, Vernacular style house with two, successive one story wings. 5x2 bays. 24'x16'. Clapboard siding, molded cornice with returns, simple corner boards. Eave central entry flanked by paired 2/2 sash. Evenly spaced 2/2 sash throughout. High marble foundation with horizontal sash. Interior brick chimney at right of ridgeline. First wing has clapboard siding, slate roof and eave central entry, flanked by 2/2 sash, interior concrete block chimney. It is fronted by an open shed roofed porch with corrugated metal roof, clapboard apron and lattice skirt. Porch replaced an older porch in 1974. Garage wing, also added in 1974, has clapboard siding, slate roof, and two eave front overhead garage doors. Concrete block foundation.

RELATED STRUCTURES: (Describe)

A c. 1900 1½ story gable roofed barn with clapboard siding and slate roof with box cornice. 26'x14'. Eave central sliding vertical plank barn door under hinged vertical plank hay door. Two spaced two light casement windows, under gable peak casement, on each gable wall. Rubblestone foundation.

STATEMENT OF SIGNIFICANCE:


Thought by the owner to have been built c. 1900, this Georgian Plan structure was the tenant house for the Gorton Farm, immediately south. The substantial nature of the building speaks to the prosperity of the Gorton family at that time. The lavish use of marble in the raised foundation is not uncommon in buildings in Danby.

REFERENCES:

personal interview, Helen Macheski; owner and life-long occupant.
The Historic Architecture of Rutland County,
Vermont Division Historic Preservation

7/19/89

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Holly Hitchcock

ORGANIZATION:

Vt Div Historic Preservation

DATE RECORDED:

7/19/89



1106-35

Vt. Division for Historic Preservation
Rutland County Danby 7/89
Macheski House, 1106-35 SW
89-A-95:17 Holly Hitchcock

89-95

17

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

SURVEY NUMBER:

1106-36

NEGATIVE FILE NUMBER:

89 A 94:20

83.A.349 (18,19)

UTM REFERENCES:

Zone/Easting/Northing

18/661045/4800010

U.S.G.S. QUAD. MAP:

Wallingford Vt. 15'

PRESENT FORMAL NAME:

ORIGINAL FORMAL NAME:

PRESENT USE: house

ORIGINAL USE: house

ARCHITECT/ENGINEER:

unknown

BUILDER/CONTRACTOR:

unknown

PHYSICAL CONDITION OF STRUCTURE:

Excellent Good

Fair Poor

STYLE: vernacular

DATE BUILT:

c. 1825

COUNTY:	Rutland
TOWN:	Danby
LOCATION:	West of TH-19, approx. .6 mi. south of Danby Village Center.
COMMON NAME:	
PROPERTY TYPE:	house
OWNER:	
ADDRESS:	
ACCESSIBILITY TO PUBLIC:	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE:	Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone Brick Concrete Concrete Block
2. Wall Structure
 - a. Wood Frame: Post & Beam Balloon
 - b. Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - c. Iron d. Steel e. Other:
3. Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Siding Brick Veneer Stone Veneer Bonding Pattern: Other:
4. Roof Structure
 - a. Truss: Wood Iron Steel Concrete
 - b. Other:
5. Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
6. Engineering Structure:
7. Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 2 1/2

Number of Bays: 4x2

Entrance Location: eave center

Approximate Dimensions: 26'x20'

SIGNIFICANCE: Architectural Historic Archeological

Historic Contexts:

Level of Significance:

Local State National

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

A 2½ story Vernacular style gable roofed residence with entry vestibule and shed roofed additions on the left gable wall and the rear. 4x2 bays. 26'x20'. Windows at main level are 1/1 with limestone lintels. Entry, second bay from left, is through a small gable roofed vestibule, with clapboard siding and corrugated metal roof. Second floor is clapboard sided, with four evenly spaced 2/2 windows, two on gable walls. Molded cornice with returns, wide frieze board. Clapboards on southern gable wall have been replaced with vinyl siding. Both shed roofed additions have vertical siding. Asphalt shingle roofs. Marble block foundation, slate roof, interior brick chimney at right of front gable slope. Exterior brick chimney on southern gable wall.


RELATED STRUCTURES: (Describe)

STATEMENT OF SIGNIFICANCE:

This c. 1825 structure is built into a hillside. The lavish use of marble in foundation construction becomes a design feature, complemented by the substantial limestone lintels of the main floor windows.

REFERENCES:

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Holly Hitchcock

ORGANIZATION:

Vt. Div. Historic Preservation

DATE RECORDED:

7/18/89



1106-36

Vt. Division for Historic Preservation
Rutland County Danby 7/89
Stewart House, 1106-36 W
89-A-94:20 Holly Hitchcock

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

SURVEY NUMBER: 1106-37
NEGATIVE FILE NUMBER: 89A94: 17,18,19; 83.A.389 #16,17
UTM REFERENCES: Zone/Easting/Northing 18/662025/4799075
U.S.G.S. QUAD. MAP: Dorset, Vt. 7.5'
PRESENT FORMAL NAME:
ORIGINAL FORMAL NAME:
PRESENT USE: community care home
ORIGINAL USE: farm
ARCHITECT/ENGINEER:
BUILDER/CONTRACTOR: unknown
PHYSICAL CONDITION OF STRUCTURE: Excellent <input type="checkbox"/> Good <input checked="" type="checkbox"/> Fair <input type="checkbox"/> Poor <input type="checkbox"/>
STYLE: Vernacular
DATE BUILT: c. 1835

COUNTY: Rutland
TOWN: Danby
LOCATION: east of TH35, approx.,.2 mi. west of junction with TH.19.
COMMON NAME: Campbell Place
PROPERTY TYPE: house
OWNER: Helen Billings
ADDRESS:
ACCESSIBILITY TO PUBLIC: Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE: Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>

GENERAL DESCRIPTION:

Structural System

- Foundation: Stone Brick Concrete Concrete Block
- Wall Structure
 - Wood Frame: Post & Beam Balloon
 - Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - Iron d. Steel e. Other:
- Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Siding Brick Veneer Stone Veneer Bonding Pattern: Other:
- Roof Structure
 - Truss: Wood Iron Steel Concrete
 - Other:
- Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
- Engineering Structure:
- Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 1 1/2

Number of Bays: 5x2

Approximate Dimensions: 30'x20'

Entrance Location: classic cottage

SIGNIFICANCE: Architectural <input checked="" type="checkbox"/> Historic <input type="checkbox"/> Archeological <input type="checkbox"/>
Historic Contexts:
Level of Significance: Local State National

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

A 1½ story vernacular style Classic Cottage farmhouse with successive wing and addition. Molded cornice, with returns. 2/2 sash throughout; small gable end windows on both gable walls. Eave central entry is fronted by shed roofed entry porch with square posts, battered wood shingled apron, and marble steps. Stone foundation, slate roof. Interior brick chimney at left of ridgeline exterior concrete block on southern gable wall. One story wing is clapboarded with slate roof and interior brick chimney; center entries on front and rear eave walls. Shed roofed addition to wing has rolled roof, clapboard siding, central vertical plank door and fixed six light sash on southern wall.

RELATED STRUCTURES: (Describe)

A. A 1½ story vernacular style tri-gable bank barn with corrugated metal gable roof and flushboard siding. C. 1860. Box cornice, corner boards. Gable right double leaf vertical plank barn doors, beneath centered hay door and gable peak opening. Ell at right rear has metal roof, flushboard siding


STATEMENT OF SIGNIFICANCE:

This c. 1835 farmhouse and associated structures are remnants of an early Danby hill farm. The specialized nature of the outbuildings--icehouse, sugarcane house, dairy barn--underline its self sufficiency. The farmhouse is a good example of an early Classic Cottage type structure and is still surrounded by the pastureland of the original farm.

REFERENCES:

personal interview, Helen Billings, owner, 7/20/89

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Holly Hitchcock

ORGANIZATION:

Vt Div. Historic Preservation

DATE RECORDED:

10/12/89

eave left hinged vertical plank doors. Small shed roofed addition on eastern gable wall of ell has metal roof, exposed rafter tails, missing pass door. Western entries to lower level, are paired double leaf vertical plank doors on western gable wall of ell, and triple sliding vertical plank doors on western eave wall of main block.

B. A one story ice-house with wood shingle gable roof, vertical plank siding, and gable center vertical plank pass door. C. 1850. 8'x10'. Two empty windows on southern eave wall.

C. A one story garage with corrugated metal gable roof and clapboard siding.

C. 1910. 10'x14'. Box cornice. Paired gable front hinged vertical plank doors; vertical plank haydoor above. Fixed, empty, sash on northern eave eall.



1106-37

Vt. Division for Historic Preservation
Rutland County Danby 7/89
Billings Farm, 1106-37 NE
89-A-94:17 Holly Hitchcock

89-94
17

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

SURVEY NUMBER:

1106-38

NEGATIVE FILE NUMBER:

89 A 94:13

UTM REFERENCES:

Zone/Easting/Northing

18/662040/4799015

U.S.G.S. QUAD. MAP:

Wallingford, Vt. 15'

PRESENT FORMAL NAME:

ORIGINAL FORMAL NAME:

PRESENT USE: house

ORIGINAL USE: house

ARCHITECT/ENGINEER:

unknown

BUILDER/CONTRACTOR:

unknown

PHYSICAL CONDITION OF STRUCTURE:

Excellent Good

Fair Poor

STYLE: vernacular

DATE BUILT:

c. 1800 / c. 1915

COUNTY: Rutland
 TOWN: Danby
 LOCATION: East of TH-35, approx. .5 mi. south of junction with TH-19.
 COMMON NAME:
 PROPERTY TYPE: duplex
 OWNER: Joe Yrsha
 ADDRESS:
 ACCESSIBILITY TO PUBLIC:
 Yes No Restricted
 LEVEL OF SIGNIFICANCE:
 Local State National

GENERAL DESCRIPTION:
 Structural System
 1. Foundation: Stone Brick Concrete Concrete Block
 2. Wall Structure
 a. Wood Frame: Post & Beam Balloon
 b. Load Bearing Masonry: Brick Stone Concrete
 Concrete Block
 c. Iron d. Steel e. Other:
 3. Wall Covering: Clapboard Board & Batten Wood Shingle
 Shiplap Novelty Asbestos Shingle Sheet Metal
 Aluminum Asphalt Siding Brick Veneer Stone Veneer
 Bonding Pattern: Other:
 4. Roof Structure
 a. Truss: Wood Iron Steel Concrete
 b. Other:
 5. Roof Covering: Slate Wood Shingle Asphalt Shingle
 Sheet Metal Built Up Rolled Tile Other:
 6. Engineering Structure:
 7. Other:
 Appendages: Porches Towers Cupolas Dormers Chimneys
 Sheds Ells Wings Bay Window Other:
 Roof Style: Gable Hip Shed Flat Mansard Gambrel
 Jerkinhead Saw Tooth With Monitor With Bellcast
 With Parapet With False Front Other:
 Number of Stories: 1½
 Number of Bays: 4x2
 Entrance Location: cape cod
 Approximate Dimensions: 24'x22'

SIGNIFICANCE: Architectural Historic Archeological

Historic Contexts:

Level of Significance:
Local State National



1106-38

Vt. Division for Historic Preservation
Rutland County Danby 7/89
Yrsha House, 1106-38 SE
89-A-94:13 Holly Hitchcock

89-94

13

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

COUNTY:	Rutland
TOWN:	Danby
LOCATION:	west of TH-35, approx. .5 miles south of junction with TH-19.
COMMON NAME:	Old Warner Farm
PROPERTY TYPE:	
OWNER:	Raymond Kapusta
ADDRESS:	
ACCESSIBILITY TO PUBLIC:	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE:	Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone Brick Concrete Concrete Block
2. Wall Structure
 - a. Wood Frame: Post & Beam Balloon
 - b. Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - c. Iron d. Steel e. Other:
3. Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Siding Brick Veneer Stone Veneer
Bonding Pattern: Other:
4. Roof Structure
 - a. Truss: Wood Iron Steel Concrete
 - b. Other:
5. Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
6. Engineering Structure:
7. Other:

Appendages: Porches Towers Cupolas Dormers Chimneys
Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel
Jerkinhead Saw Tooth With Monitor With Bellcast
With Parapet With False Front Other:

Number of Stories: 1½

Number of Bays: 5x2 Entrance Location: classic cottage

Approximate Dimensions: 24'x18'

SURVEY NUMBER:	1106-39
NEGATIVE FILE NUMBER:	89 A 94:14,15
UTM REFERENCES:	Zone/Easting/Northing 18/662020/4799020
U.S.G.S. QUAD. MAP:	Wallingford Vt 15'
PRESENT FORMAL NAME:	
ORIGINAL FORMAL NAME:	
PRESENT USE:	house
ORIGINAL USE:	house
ARCHITECT/ENGINEER:	
BUILDER/CONTRACTOR:	unknown
PHYSICAL CONDITION OF STRUCTURE:	Excellent <input type="checkbox"/> Good <input checked="" type="checkbox"/> Fair <input type="checkbox"/> Poor <input type="checkbox"/>
STYLE:	vernacular
DATE BUILT:	c.1880

SIGNIFICANCE: Architectural <input checked="" type="checkbox"/> Historic <input type="checkbox"/> Archeological <input type="checkbox"/>	
Historic Contexts:	Level of Significance: Local State National

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

A 1½ story Vernacular style Classic Cottage type residence with two successive gable roofed wings. 5x2 bays. 24'x18'. Clapboard siding, simple corner boards, molded cornice with wide frieze board. Eave central entry with entablature is flanked by 2/2 windows with peaked lintelboards, below kneewall windows. Set back 1½ story wing, 3x2 bays, repeats lintelboards, kneewall windows, and eave central entry. It is fronted by open porch with new, square posts. Stone foundation, slate roof, central brick chimneys on main block and first wing. One story gable roofed wing at extreme left has eave central entry with new two light sash to the right. Clapboard siding, slate roof, and concrete foundation.

RELATED STRUCTURES: (Describe)

A. 1½ story gable roofed barn with small shed roofed addition across the rear gable wall. 14'x28'. Clapboard siding, corner boards, box cornice. Sliding vertical plank door on northern eave wall. Small four light casement on front gable wall, nine light casement in rear gable peak. Clapboarded, with slate roof. Shed addition has narrow clapboard siding, box cornice, and slate


STATEMENT OF SIGNIFICANCE:

This c. 1880 structure, known locally as The Old Warner Farm, is a good example of an early Classic Cottage type. Although TH 35 now is a dead end road, it was once the stagecoach road to Manchester. A small headstone in the nearby woods, marks the resting spot of an early Warner child who died during a winter in which great quantities of snow made transportation to the Danby Cemetery impossible.

REFERENCES:

Personal interview, Paul Pearce, lifelong resident 7/12/89

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Holly Hitchcock

ORGANIZATION:

Vt Div. Historic Preservation

DATE RECORDED:

7/13/89

RELATED STRUCTURES CONTINUED:

roof. Rear hinged vertical plank entry door, with eight casement to the right. Cobblestone foundation throughout. Structure was moved here from another site.

B. C. 1940 Garage, slate covered gable roof. Clapboard siding.



1106-39

89-94

Vt. Division for Historic Preservation
Rutland County Danby 7/89
Warner House, 1106-39 W
89-A-94:14 Holly Hitchcock

POOR QUALITY

ORIGINAL_____

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
District Complex Survey Form

SURVEY NUMBER: 1106-40
NEGATIVE FILE NUMBER(S): 89 A 94: 10,11,12
UTM REFERENCES: Zone/Easting/Northing A B 18/662015/4799020 C D
U.S.G.S. QUAD. MAP: Wallingford, VT. 15'

COUNTY: Rutland
TOWN: Danby
LOCATION: South of Quarry Hill Rd. p.2) approx,.1 mile west of jct. with TH-35.
NAME OF DISTRICT:
TYPE OF DISTRICT:
PHYSICAL CONDITION OF STRUCTURES: Excellent % Good 100% Fair % Poor %
LEVEL OF SIGNIFICANCE: Local <input checked="" type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>
HISTORIC CONTEXTS: Quarrying & Stone. Milling

COMPLEX INFORMATION ONLY	
COMMON NAME: Quarry Hill	
PRESENT FORMAL NAME:	
ORIGINAL FORMAL NAME: VT. Marble Co. Worker's Housing	
TYPE OF COMPLEX:	
TYPES OF STRUCTURES: house, duplexes	
PRESENT USE: residential	
ORIGINAL USE: workers housing	
ARCHITECT/ENGINEER: unknown	
BUILDER/CONTRACTOR: VT Marble Company	
ACCESSIBILITY TO PUBLIC: Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>	

STATEMENT OF SIGNIFICANCE:

These three c. 1905 structures, with their Queen Anne style porches, were originally built as company housing for workers at the Danby marble industry, during a period of renewed activity. New privately owned, they are little changed and serve as a reminder of the preeminence of the marble industry during this period of Danby's history.

89 A 94: 10,11,12

18/662015/4799020

Wallingford, VT. 15'

Rutland
Danby
South of Quarry Hill Rd. p.2)
approx,.1 mile west of jct. with TH-35.

Quarry Hill

VT. Marble Co. Worker's Housing

house, duplexes

100

residential
workers housing

unknown

VT Marble Company

Quarrying & Stone. Milling

These three c. 1905 structures, with their Queen Anne style porches, were originally built as company housing for workers at the Danby marble industry, during a period of renewed activity. New privately owned, they are little

MAP



Danby Village

TH-35

U.S. 7

TH-35

Quarry Hill Road
(CP-2)



Danby

Mount Tabor

BOUNDARY DESCRIPTION:

REFERENCES:

The Historic Architecture of Rutland County,
Vermont Division Historic Preservation

RECORDED BY:
Holly Hitchcock

ORGANIZATION:
VT Div. Historic Preservation

DATE RECORDED:
11/21/89

OUTSTANDING COMPONENTS OF DISTRICT <input type="checkbox"/> COMPLEX <input type="checkbox"/>		
(Include individual survey number ONLY if surveyed individually.)		
MAP NUMBER: A	DATE BUILT: c1905	SURVEY NUMBER: 1106-40
FUNCTIONAL TYPE: house		NEGATIVE FILE NUMBER: 89A94:10
COMMON NAME:		OWNER: D.W. Kellcher
HISTORIC CONTEXTS:		
DESCRIPTION: A 2½ story Queen Anne style tri-gable ell residence, with front entry porch and new side deck. 2x2 bays. 15'x18'. Clapboard siding, corner boards, molded cornice with returns. Primary entrance is gable right on main block. Secondary entrance is gable right on ell. Fenestration has been altered for conversion to multi-family dwelling; however eave wall and gable front retain evenly spaced 6/6 sash. Other sash are 1/1 ; new shutters through- out. Queen Anne style entry porch has slate shed roof, scrollsawn brackets, balustrade with diagonal bracing, turned columns, lattice skirt, and exposed rafter tails. New open deck fronting ell gable wall has straight balustrade		
MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:		NEGATIVE FILE NUMBER:
COMMON NAME:		OWNER:
HISTORIC CONTEXTS:		
DESCRIPTION: and lattice skirt. Brick-faced, stone foundation, slate roof, interior brick chimneys on both main block and ell. New stairways to second floor level at front and rear enter doorways which are former window sites.		
MAP NUMBER: B	DATE BUILT: c1905	SURVEY NUMBER: 1106-40
FUNCTIONAL TYPE: duplex		NEGATIVE FILE NUMBER: 89A94:11
COMMON NAME:		OWNER: Edward Jaworski
HISTORIC CONTEXTS:		
DESCRIPTION: A 2½ story vernacular style gable roofed duplex with front entry porch and shed roofed rear additions. 6x2 bays. 40'x20'. Clapboard siding, corner boards, box cornice. Two eave central entries are flanked by two 2/2 windows. Four evenly spaced 2/2 windows at second floor level. Queen Anne style porch fronting entry has slate shed roof, spindle valance balustrade with diamond ornamenton diagonal supports, turned columns, and lattice skirt. Rear entry is through one story shed roofed additions at both eave wall ends. Foundation, which does not extend beneath additions, is stone; slate roof-- asphalt shingle on additions, interior brick chimneys at both		
MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:		NEGATIVE FILE NUMBER:
COMMON NAME:		OWNER:
HISTORIC CONTEXTS:		
DESCRIPTION: ridgeline. ends.		

OUTSTANDING COMPONENTS OF DISTRICT COMPLEX
(Include individual survey number ONLY if surveyed individually.)

MAP NUMBER: C	DATE BUILT: c1905	SURVEY NUMBER: 1106-40
FUNCTIONAL TYPE: duplex	NEGATIVE FILE NUMBER: 89A94:12	
COMMON NAME:	OWNER: Edward Jaworski	

HISTORIC CONTEXTS:

DESCRIPTION:
B. Identical to A., except for new front entrance doors with fanlight insets, straight balustrade on front entry porch.
Foundation has been added under right rear addition.

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	

HISTORIC CONTEXTS:

DESCRIPTION:

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	

HISTORIC CONTEXTS:

DESCRIPTION:

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	

HISTORIC CONTEXT:

DESCRIPTION:



1106-40 #A

89-94
10

Vt. Division for Historic Preservation
Rutland County Danby 7/89
Vt. Marble Co. Housing, 1106-40 #A SE
89-A-94:10 Holly Hitchcock



1106-40 #B

Vt. Division for Historic Preservation
Rutland County Danby 7/89
Vt. Marble Co. Housing, 1106-40 #B S
89-A-94:11 Holly Hitchcock

89-94

11



1106-40 #C

89-94

12

Vt. Division for Historic Preservation
Rutland County Danby 7/89
Vt. Marble Co. Housing, 1106-40 #C E
89-A-94:12 Holly Hitchcock

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

SURVEY NUMBER: 1106- 41
NEGATIVE FILE NUMBER: 89 A 92:23 <i>83.A.388 (9)</i>
UTM REFERENCES: Zone/Easting/Northing 18/661990/4800920
U.S.G.S. QUAD. MAP: Dorset, Vt. 7.5'
PRESENT FORMAL NAME:
ORIGINAL FORMAL NAME:
PRESENT USE: house
ORIGINAL USE: house
ARCHITECT/ENGINEER:
BUILDER/CONTRACTOR:
PHYSICAL CONDITION OF STRUCTURE: Excellent <input type="checkbox"/> Good <input type="checkbox"/> Fair <input checked="" type="checkbox"/> Poor <input type="checkbox"/>
STYLE: Vernacular
DATE BUILT: c.1885

COUNTY: Rutland
TOWN: Danby
LOCATION: North of TH-1, at junction with TH-33. Danby Historic District A.
COMMON NAME:
PROPERTY TYPE: house
OWNER: E. Millard
ADDRESS:
ACCESSIBILITY TO PUBLIC: Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE: Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>

GENERAL DESCRIPTION:

Structural System

- Foundation: Stone Brick Concrete Concrete Block
- Wall Structure
 - Wood Frame: Post & Beam Balloon
 - Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - Iron d. Steel e. Other:
- Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Siding Brick Veneer Stone Veneer Bonding Pattern: Other:
- Roof Structure
 - Truss: Wood Iron Steel Concrete
 - Other:
- Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
- Engineering Structure:
- Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 2½

Number of Bays: 3x2 Entrance Location: eave left

Approximate Dimensions: 18'x12'

SIGNIFICANCE: Architectural <input checked="" type="checkbox"/> Historic <input type="checkbox"/> Archeological <input type="checkbox"/>
Historic Contexts:
Level of Significance: Local State National

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

A 2½ story Vernacular style gable roofed residence with two story shed roofed addition and front wraparound porch. 3x2 bays. 18'x12'. Clapboard siding, simple corner boards, molded cornice, and wide freize boards. Original vertical plank entry door at eave front left is no longer used; entry is now through addition. 2/2 sash with simple surrounds throughout. Queen Anne style porch crosses front and wraps around to the right rear, where it intersects with addition. Porch has scrollsawn brackets, turned columns, a straight balustrade, marble steps. Marble and stone foundation, corrugated metal roof, interior brick chimneys at center of ridgeline and right rear of main block.


RELATED STRUCTURES: (Describe)

STATEMENT OF SIGNIFICANCE:

This c. 1885 structure near the center of Danby Village is a good example of a modest late 19th. century residence. The extensive use of marble in the foundation, steps, and walk indicate the availability of the material.

REFERENCES:

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:
Holly Hitchcock

ORGANIZATION:
Vt Div Historic Preservation

DATE RECORDED:
7/5/89



1106-41

89-92

23

Vt. Division for Historic Preservation
Rutland County Danby 7/89
Millard House, 1106-41 NW
89-A-92:23 Holly Hitchcock

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

SURVEY NUMBER: 1106-42
NEGATIVE FILE NUMBER: 89 A 92:20 83.A.388 #10
UTM REFERENCES: Zone/Easting/Northing 18/661950/4800840
U.S.G.S. QUAD. MAP: Dorset, Vt. 7.5'
PRESENT FORMAL NAME:
ORIGINAL FORMAL NAME:
PRESENT USE: house
ORIGINAL USE: house
ARCHITECT/ENGINEER: unknown
BUILDER/CONTRACTOR: unknown
PHYSICAL CONDITION OF STRUCTURE: Excellent <input type="checkbox"/> Good <input checked="" type="checkbox"/> Fair <input type="checkbox"/> Poor <input type="checkbox"/>
STYLE: Greek Revival
DATE BUILT: c. 1835

COUNTY: Rutland
TOWN: Danby
LOCATION: South of TH-1, approx, 1/2 mile west of junction with TH-33. Danby Historic District A.
COMMON NAME:
PROPERTY TYPE: house
OWNER:
ADDRESS:
ACCESSIBILITY TO PUBLIC: Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE: Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>

GENERAL DESCRIPTION:

Structural System

- Foundation: Stone Brick Concrete Concrete Block
- Wall Structure
 - Wood Frame: Post & Beam Balloon
 - Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - Iron d. Steel e. Other:
- Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Siding Brick Veneer Stone Veneer Bonding Pattern: Other:
- Roof Structure
 - Truss: Wood Iron Steel Concrete
 - Other:
- Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
- Engineering Structure:
- Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 1 1/2

Number of Bays: 4x2

Approximate Dimensions: 22'x20'

Entrance Location: 3/4 classic cottage

SIGNIFICANCE: Architectural <input checked="" type="checkbox"/> Historic <input type="checkbox"/> Archeological <input type="checkbox"/>
Historic Contexts:
Level of Significance: Local State National

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

A 1½ story Greek Revival 3/4 classic cottage. c. 1835. 4x2 bays. 22'x20'. Rear wing and open deck. Clapboard siding, molded cornice with returns, wide returns, wide entablature,. Vertical plank entry door, second bay from left, has full entablature, corner block molding and four light transom. 2/2 sash throughout House is sited on hillside with marble foundation housing full basement Slate roof, exterior brick chimney on left gable wall. Two story gableroofted ell at rear left houses garage with overhead garage door at basement. New, open deck at main level, rear right. Marble coping fronts foundation.


RELATED STRUCTURES: (Describe)

STATEMENT OF SIGNIFICANCE:

Typical of the modest homes of mill operatives of the time, this structure retains its early characteristics. As is true for many structures in Danby, marble is used lavishly for many structural details.

REFERENCES:

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Holly Hitchcock

ORGANIZATION:

Vt Div. Historic Preservation

DATE RECORDED:

7/5/89



1106-42

Vt. Division for Historic Preservation
Rutland County Danby 7/89
House, 1106-42 E
89-A-92:20 Holly Hitchcock

89-92

20

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

SURVEY NUMBER:
1106-43

NEGATIVE FILE NUMBER:
89 A 92:19 83A 392 # 21

UTM REFERENCES:
Zone/Easting/Northing
18/661910/4800910

U.S.G.S. QUAD. MAP:
Dorset, Vt. 7.5'

PRESENT FORMAL NAME:

ORIGINAL FORMAL NAME:

PRESENT USE: house

ORIGINAL USE: house

ARCHITECT/ENGINEER:
unknown

BUILDER/CONTRACTOR:
unknown

PHYSICAL CONDITION OF STRUCTURE:
Excellent Good
Fair Poor

STYLE: Vernacular Federal

DATE BUILT:
c. 1830

COUNTY: Rutland

TOWN: Danby

LOCATION: North of TH-33, approx. .1mi.
west of jct. with TH-1. Danby Historic
District A.

COMMON NAME:

PROPERTY TYPE: house

OWNER:
ADDRESS:

ACCESSIBILITY TO PUBLIC:
Yes No Restricted

LEVEL OF SIGNIFICANCE:
Local State National

GENERAL DESCRIPTION:

Structural System

- Foundation: Stone Brick Concrete Concrete Block
- Wall Structure
 - Wood Frame: Post & Beam Balloon
 - Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - Iron d. Steel e. Other:
- Wall Covering: Clapboard Board & Batten Wood Shingle
Shiplap Novelty Asbestos Shingle Sheet Metal
Aluminum Asphalt Siding Brick Veneer Stone Veneer
Bonding Pattern: Other:
- Roof Structure
 - Truss: Wood Iron Steel Concrete
 - Other:
- Roof Covering: Slate Wood Shingle Asphalt Shingle
Sheet Metal Built Up Rolled Tile Other:
- Engineering Structure:
- Other:

Appendages: Porches Towers Cupolas Dormers Chimneys
Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel
Jerkinhead Saw Tooth With Monitor With Bellcast
With Parapet With False Front Other:

Number of Stories: 1 1/2

Number of Bays: 4x2 Entrance Location: 3/4 classic cottage

Approximate Dimensions: 20'x18'

SIGNIFICANCE: Architectural Historic Archeological

Historic Contexts: Level of Significance:
Local State National

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

A 1½ story Federal style 3/4 classic cottage. 4x2 bays. 20'x18'. Two successive one story wings to the left. Clapboard siding, molded cornice with returns, simple corner boards. Entry with entablature and new metal door hood is at second bay from left; new 1/1 sash, with occasional 6/6. Simple door and window surrounds. High, concrete -faced stone foundation, asphalt shingle roof and central brick chimney. Marble steps and retaining wall fronting property. First wing has clapboard siding, rolled roofing, and vertical plank double leaf doors; second wing has stucco walls, rolled roofing and 6/6 sash. Concrete block foundation.


RELATED STRUCTURES: (Describe)

STATEMENT OF SIGNIFICANCE:

Built c. 1830, during a period of increasing quarrying activity at nearby Dorset Mountain, this structure typifies the modest homes of mill operatives. Marble is used extensively for foundation, steps, and retaining wall. Other than sash changes, the structure is only slightly altered.

REFERENCES:

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Holly Hitchcock

ORGANIZATION:

Vt Div Historic Preservation

DATE RECORDED:

7/5/89



1106-43

Vt. Division for Historic Preservation
Rutland County Danby 7/89
Vernacular Fed. Style Hse., 1106-43 NE
89-A-92:19 Holly Hitchcock

89-92

19

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

SURVEY NUMBER: 1106- 45
NEGATIVE FILE NUMBER: 89 A 92:22 <i>P3.A.3ff # 12</i>
UTM REFERENCES: Zone/Easting/Northing 18/661830/4800680
U.S.G.S. QUAD. MAP: Dorset, Vt. 7.5'
PRESENT FORMAL NAME:
ORIGINAL FORMAL NAME:
PRESENT USE: house
ORIGINAL USE: house
ARCHITECT/ENGINEER: unknown
BUILDER/CONTRACTOR: unknown
PHYSICAL CONDITION OF STRUCTURE: Excellent <input type="checkbox"/> Good <input checked="" type="checkbox"/> Fair <input type="checkbox"/> Poor <input type="checkbox"/>
STYLE: vernacular
DATE BUILT: c. 1890

COUNTY: Rutland
TOWN: Danby
LOCATION: South of TH-1, approx..2mi. west of Danby Center & Historic District A.
COMMON NAME:
PROPERTY TYPE: house
OWNER: ADDRESS:
ACCESSIBILITY TO PUBLIC: Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE: Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>

GENERAL DESCRIPTION:

Structural System

- Foundation: Stone Brick Concrete Concrete Block
- Wall Structure
 - Wood Frame: Post & Beam Balloon
 - Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - Iron d. Steel e. Other:
- Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Siding Brick Veneer Stone Veneer Bonding Pattern: Other:
- Roof Structure
 - Truss: Wood Iron Steel Concrete
 - Other:
- Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
- Engineering Structure:
- Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 2 1/2

Number of Bays: 3x2 Entrance Location: eave center

Approximate Dimensions: 20'x18'

SIGNIFICANCE: Architectural Historic Archeological

Historic Contexts:	Level of Significance: Local State National
--------------------	--

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

A 2½ story Vernacular style gable roofed residence with a one story wing to the left, shedroofed addition at the left rear, and porches fronting main block and wing. 3x2 bays. 20'x18'. Clapboard siding, box cornice, simple corner boards. Eave center entry is flanked by 2/2 sash. Simple door and window surrounds drip molding. Queen Anne style porch fronting main block has scrollsawn brackets, turned posts, straight balustrade, and lattice skirt. Marble steps. Open porch fronting wing has straight balustrade. New rear addition is clapboarded with corrugated metal roof. Marble block foundation, slate roof, interior brick chimney slightly left of center. Exterior concrete chimney at right rear.

RELATED STRUCTURES: (Describe)


C1930 A small shed-roofed shed with wood shingle siding and corrugated metal roof. Vertical plank double leaf doors on front wall, fixed six light window on right wall.

STATEMENT OF SIGNIFICANCE:

This modest c. 1890 residence, with its attractive Queen Anne style porch, presents a stylistic departure from its many Greek Revival style neighbors. It is one of the few structures on Borough Hill built after the bankruptcy of the railroad in 1857, with the resulting collapse of the marble industry.

REFERENCES:

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:
Holly Hitchcock

ORGANIZATION:
Vt Div. Historic Preservation

DATE RECORDED:
7/6/89



1106-45

89-92

22

Vt. Division for Historic Preservation
Rutland County Danby 7/89
Vernacular House, 1106-45 SE
89-A-92:22 Holly Hitchcock

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

SURVEY NUMBER: 1106-46
NEGATIVE FILE NUMBER: 89 A 92:21 83-A-388 # 13
UTM REFERENCES: Zone/Easting/Northing 18/661780/4800610
U.S.G.S. QUAD. MAP: Dorset, Vt. 7.5'
PRESENT FORMAL NAME:
ORIGINAL FORMAL NAME:
PRESENT USE: house
ORIGINAL USE: house
ARCHITECT/ENGINEER: unknown
BUILDER/CONTRACTOR: unknown
PHYSICAL CONDITION OF STRUCTURE: Excellent <input type="checkbox"/> Good <input checked="" type="checkbox"/> Fair <input type="checkbox"/> Poor <input type="checkbox"/>
STYLE: Greek Revival
DATE BUILT: c. 1845

COUNTY: Rutland
TOWN: Danby
LOCATION: South of TH-1, approx. .3mi. west of Danby Center & Historic District A.
COMMON NAME:
PROPERTY TYPE: house
OWNER: ADDRESS:
ACCESSIBILITY TO PUBLIC: Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE: Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>

GENERAL DESCRIPTION:

Structural System

- Foundation: Stone Brick Concrete Concrete Block
- Wall Structure
 - Wood Frame: Post & Beam Balloon
 - Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - Iron d. Steel e. Other:
- Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Siding Brick Veneer Stone Veneer Bonding Pattern: Other:
- Roof Structure
 - Truss: Wood Iron Steel Concrete
 - Other:
- Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
- Engineering Structure:
- Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 2½

Number of Bays: 5x2 Entrance Location: Georgian plan

Approximate Dimensions: 22'x18'

SIGNIFICANCE: Architectural <input checked="" type="checkbox"/> Historic <input type="checkbox"/> Archeological <input type="checkbox"/>
Historic Contexts:
Level of Significance: Local State National

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

A 2½ story Georgian Plan Greek Revival style residence with one story rear ell. 22'x18'. Aluminum siding obscures certain details. Molded cornice with returns. Wide freize board. 2/2 replacement sash, with one 6/6 window remaining in gable peak. Recessed eave central entry with entablature has panelled pilasters, marble steps, and new wrought iron handrails. Marble foundation. slate roof, and interior concrete block chimney, slightly right of center. The ell, at the rear left, has clapboard siding, a central brick chimney, and a vertical plank entry door at the right rear.


RELATED STRUCTURES: (Describe)

STATEMENT OF SIGNIFICANCE:

This substantial c. 1845 residence is one of many Greek Revival style structure on Borough Hill. It is a good example of a Georgian Plan residence, dating from Danby's period of greatest prosperity. Marble is used for the steps and foundation.

REFERENCES:

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land
- Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Holly Hitchcock

ORGANIZATION:

Vt Div. Historic Preservation

DATE RECORDED:

7/6/89



1106-46

89-92

21

Vt. Division for Historic Preservation
Rutland County Danby 7/89
Greek Rev. Hse., 1106-46 NE
89-A-92:21 Holly Hitchcock

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

SURVEY NUMBER: 1106-47
NEGATIVE FILE NUMBER: 89 A 173:2A 83A 384 #14
UTM REFERENCES: Zone/Easting/Northing 18/661710/4800700
U.S.G.S. QUAD. MAP: Dorset, Vt. 7.5'
PRESENT FORMAL NAME:
ORIGINAL FORMAL NAME:
PRESENT USE: house
ORIGINAL USE: house
ARCHITECT/ENGINEER: unknown
BUILDER/CONTRACTOR: unknown
PHYSICAL CONDITION OF STRUCTURE: Excellent <input type="checkbox"/> Good <input checked="" type="checkbox"/> Fair <input type="checkbox"/> Poor <input type="checkbox"/>
STYLE: Greek Revival
DATE BUILT: c. 1855

COUNTY: Rutland
TOWN: Danby
LOCATION: West of spur joining TH-33 and TH-1, approx. .2 mi. west of Danby Center Historic District A.
COMMON NAME:
PROPERTY TYPE: house
OWNER:
ADDRESS:
ACCESSIBILITY TO PUBLIC: Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE: Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>

GENERAL DESCRIPTION:

Structural System

- Foundation: Stone Brick Concrete Concrete Block
- Wall Structure
 - Wood Frame: Post & Beam Balloon
 - Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - Iron d. Steel e. Other:
- Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Siding Brick Veneer Stone Veneer Bonding Pattern: Other:
- Roof Structure
 - Truss: Wood Iron Steel Concrete
 - Other:
- Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
- Engineering Structure:
- Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 1½

Number of Bays: 5x2

Approximate Dimensions: 20'x18'

Entrance Location: classic cottage

SIGNIFICANCE: Architectural <input checked="" type="checkbox"/> Historic <input type="checkbox"/> Archeological <input type="checkbox"/>
Historic Contexts:
Level of Significance: Local State National

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

A 1½ story Greek Revival style classic cottage. C. 1855. 5x2 bays. 20'x18'. Aluminum sided, molded cornice, and panelled corner pilasters. Regularly spaced 2/2 sash with peaked lintel boards. Recessed eave central entry has full entablature, panelled pilasters, and marble steps. Marble foundation, slate roof, and exterior brick chimney on right eave wall. Marble retaining wall fronts property.

RELATED STRUCTURES: (Describe)


A gable roofed garage with aluminum siding and asphalt shingle roof. C. 1950. Noncontributing due to age.

STATEMENT OF SIGNIFICANCE:

This c.1855 classic cottage is one of many attractive Greek Revival style houses built in Danby during its period of greatest prosperity. It is a good example of its type. Marble is used extensively in the foundation, steps, and front retaining wall. Borough Hill, where the house is located, is the point of origin for Mill Brook, along which intensive quarrying began in the 1830's.

REFERENCES:

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Holly Hitchcock

ORGANIZATION:

Vt Div. Historic Preservation

DATE RECORDED:

7/6/89



1106-47

Vt. Division for Historic Preservation
Rutland County Danby 9/89
House, 1106-47 --
89-A-173:3 Holly Hitchcock

89-173

2A 3

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

SURVEY NUMBER: 1106-48
NEGATIVE FILE NUMBER: 89 A 95:16
UTM REFERENCES: Zone/Easting/Northing 18/660820/4801320
U.S.G.S. QUAD. MAP: Dorset, Vt. 7.5'
PRESENT FORMAL NAME:
ORIGINAL FORMAL NAME:
PRESENT USE: house
ORIGINAL USE: house
ARCHITECT/ENGINEER: unknown
BUILDER/CONTRACTOR: unknown
PHYSICAL CONDITION OF STRUCTURE: Excellent <input type="checkbox"/> Good <input checked="" type="checkbox"/> Fair <input type="checkbox"/> Poor <input type="checkbox"/>
STYLE: vernacular
DATE BUILT: c. 1890

COUNTY: Rutland
TOWN: Danby
LOCATION: north of TH-33, approx. .6 miles east of junction with TH-15.
COMMON NAME: Mathewson House
PROPERTY TYPE: house
OWNER: Annie Rothman
ADDRESS:
ACCESSIBILITY TO PUBLIC: Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE: Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>

GENERAL DESCRIPTION:

Structural System

- Foundation: Stone Brick Concrete Concrete Block
- Wall Structure
 - Wood Frame: Post & Beam Balloon
 - Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - Iron d. Steel e. Other:
- Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Siding Brick Veneer Stone Veneer Bonding Pattern: Other:
- Roof Structure
 - Truss: Wood Iron Steel Concrete
 - Other:
- Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
- Engineering Structure:
- Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 2 1/2

Number of Bays: 5x2 Entrance Location: Georgian Plan center

Approximate Dimensions: 24'x18'

SIGNIFICANCE: Architectural <input checked="" type="checkbox"/> Historic <input type="checkbox"/> Archeological <input type="checkbox"/>
Historic Contexts:
Level of Significance: Local State National

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

A 2½ story Vernacular style gable roofed residence with right rear wing and ell, and open front porch. 5x2 bays. 24'x18'. Clapboard siding, molded cornice, corner boards. Eave central entry through Queen Anne style porch with slate hip roof, spindle valance, turned columns, and lattice skirt. Evenly spaced 2/2 sash with shutters throughout. Narrow three sided bay window on eastern gable wall, in front of intersection with wing. 2½ story wing and ell are clapboarded with irregularly spaced and sized windows; most have 2/2 sash with shutters. Brick foundation at main block; stone at wing and ell. Slate roofs. Interior brick chimney at ell ; Exterior brick Colonial Revival style chimney on western gable wall of main block.

RELATED STRUCTURES: (Describe)

- A. A one story gable roofed corn crib with shed roofed addition. Vertical slat siding, slate roof on both sections. Hinged vertical plank pass door on gable front, open doorway to addition. Rubblestone foundation. C. 1890.
- B. A one story gable roofed garage with clapboard siding and slate roof. New overhead door on gable front, fixed six light casement on both eave walls.


STATEMENT OF SIGNIFICANCE:

Although this c. 1900 residence is locally called the Matthewson House, and the 1869 Beers Map shows the owner as A.A. Matthewson, the present structure was built c. 1900 on the foundation of the previous building. Once a 170 acre working farm, the site retains several of its original outbuildings.

REFERENCES:

Personal interview, Annie Rothman, owner and local historian 7/18/89

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Holly Hitchcock

ORGANIZATION:

Vt Div. Historic Preservation

DATE RECORDED:

7/19/89

RELATED STRUCTURES CONTINUED:

Concrete foundation. C. 1925.

C. A one story gable roofed milkhouse with clapboard siding and slate roof.

Small openings missing sash on both eave walls and southern gable wall;
vertical plank pass door on northern gable wall. Rubblestone foundation. C. 1890.



1106-48

Vt. Division for Historic Preservation
Rutland County Danby 7/89
Rothman House, 1106-48 NE
89-A-95:16 Holly Hitchcock

89-95

16

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

SURVEY NUMBER:

1106-49

NEGATIVE FILE NUMBER:

89 A 95 :14,15

UTM REFERENCES:

Zone/Easting/Northing

18/659930/4801420

U.S.G.S. QUAD. MAP:

Dorset, Vt. 7.5'

PRESENT FORMAL NAME:

ORIGINAL FORMAL NAME:

PRESENT USE: house

ORIGINAL USE: house

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

George Wilbur

PHYSICAL CONDITION OF STRUCTURE:

Excellent Good

Fair Poor

STYLE: Greek Revival

DATE BUILT:

c1825

COUNTY: Rutland

TOWN: Danby

LOCATION: West of TH-15, approx. .1mi.
north of junction with TH-31 & TH-33.

COMMON NAME:

PROPERTY TYPE: house

OWNER: Ron Neuman

ADDRESS:

ACCESSIBILITY TO PUBLIC:

Yes No Restricted

LEVEL OF SIGNIFICANCE:

Local State National

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone Brick Concrete Concrete Block
2. Wall Structure
 - a. Wood Frame: Post & Beam Balloon
 - b. Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - c. Iron d. Steel e. Other:
3. Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Siding Brick Veneer Stone Veneer Bonding Pattern: Other:
4. Roof Structure
 - a. Truss: Wood Iron Steel Concrete
 - b. Other:
5. Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
6. Engineering Structure:
7. Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 1 1/2

Number of Bays: 5x2

Entrance Location: classic cottage

Approximate Dimensions: 30'x20'

SIGNIFICANCE: Architectural Historic Archeological

Historic Contexts:

Level of Significance:

Local State National

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

A 1½ story Greek Revival style Classic Cottage, with large 1½ story wing setback and to the right. 5x2 bays. 30'x20'. New clapboard siding replaces wood shingle siding. Molded cornice with returns, wide frieze board, panelled corner pilasters. Wave central entry with entablature, four light transom, 2/3 sidelights, and pilasters is flanked by 8/8 windows with peaked lintel-boards. Other window surrounds are simple. Gable roofed entry porch has molded cornice, dentilwork, and Tuscan columns. 4x2 bay, 40'x20' gable roofed wing has eave left entry, flanked by 8/8 windows, below three kneewall windows; new tripartite window on the right. The molded cornice is less ornate than the main block; however a new gable roofed doorhood echoes the dentilwork of the main block porch. Marble foundation, slate roofs, interior brick chimneys on both main block and wing.

RELATED STRUCTURES: (Describe)

The c. 1850 gable roofed barn is 1½ stories with clapboard siding and slate roof. Eave center opening once housed sliding barn door; three small, stable windows is in right gable peak, below hoist. Carried to this spot by a tornado, the foundation is minimal; however the structure has been stabilized.


STATEMENT OF SIGNIFICANCE:

This Greek Revival structure was built for George Geogr Wilbur, an early Danby resident, and "G.J.W." 1822" is inscribed on the marble entrance stone. The Greek Revival detailing may have been added by a later owner, J.T. Griffith, who appears as owner in Chose's map of 1859. Two barns, one no longer standing, would also have been constructed at about this time. It is thought that the wing of the structure was once a cheese factory.

REFERENCES:

Personal interview, Ron Neuman, owner, 7/18/89
Chose's Map of 1859 The Historic Architecture of Rutland County. V.D.H.P.

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Holly Hitchcock

ORGANIZATION:

Vt. Div. Historic Preservation

DATE RECORDED:

7/19/89



1106-49

89-95

14

Vt. Division for Historic Preservation
Rutland County Danby 7/89
Newman House, 1106-49 SW
89-A-95:14 Holly Hitchcock

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

SURVEY NUMBER:

1106-50

NEGATIVE FILE NUMBER:

89A95:13

UTM REFERENCES:

Zone/Easting/Northing

18/659260/4800970

U.S.G.S. QUAD. MAP:

Wallingford, Vt. 15'

PRESENT FORMAL NAME:

Danby Hill Farm

ORIGINAL FORMAL NAME:

COUNTY: Rutland

TOWN: Danby

LOCATION: north of TH-31, approx. .7
miles east of junction with TH-1.

COMMON NAME:

Old Feltz Place

PROPERTY TYPE: barn

OWNER: Nick Ihasz
ADDRESS:

ACCESSIBILITY TO PUBLIC:

Yes No Restricted

LEVEL OF SIGNIFICANCE:

Local State National

PRESENT USE: barn

ORIGINAL USE: barn

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:

Excellent Good

Fair Poor

STYLE: vernacular

DATE BUILT:

c. 1830

GENERAL DESCRIPTION:

Structural System

- 1. Foundation: Stone Brick Concrete Concrete Block
- 2. Wall Structure
 - a. Wood Frame: Post & Beam Balloon
 - b. Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - c. Iron d. Steel e. Other:
- 3. Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Siding Brick Veneer Stone Veneer Bonding Pattern: Other:
- 4. Roof Structure
 - a. Truss: Wood Iron Steel Concrete
 - b. Other:
- 5. Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
- 6. Engineering Structure:
- 7. Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 1 1/2

Number of Bays: 5x10

Entrance Location: gable center

Approximate Dimensions: 40'x60'

SIGNIFICANCE: Architectural Historic Archeological

Historic Contexts:

Level of Significance:

Local State National

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

A 1½ story vernacular style gable roofed bank barn with vertical plank siding and corrugated metal roof. 40'x60'. Sliding, vertical plank doors at gable front, beneath haydoor at second floor level, and loft opening in gable peak. One story milkhouse ell, on eastern eave wall, has slate roof and clapboard siding. One story wing at gable left has corrugated metal roof and clapboard siding. Irregularly spaced windows along western eave wall have various sash. Ornamental metal ventilator is centered at ridgeline.

RELATED STRUCTURES: (Describe)

- A. The reproduction Greek Revival style, Georgian plan house at this site was built c. 1950, and is, therefore, non-contributing, due to age.
- B. A c.1880 one story vernacular style barn with vertical plank siding and corrugated metal gable roof. 16'x18'. Eave center, sliding, vertical plank barn doors. A third barn no longer standing.


STATEMENT OF SIGNIFICANCE:

This large c. 1830 bank barn is a tribute to the vitality of agriculture in Danby during the early 1800's. The related c. 1950 house recreates the feeling of the original farmhouse, and, in conjunction with the remaining barns and pastureland, evokes a sense of a large, prosperous early hill farm.

REFERENCES:

personal interview, Nick Ihasz, owner, 7/18/89

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Holly Hitchcock

ORGANIZATION:

Vt Div. Historic Preservation

DATE RECORDED:

7/20/89



NO PICTURES ASSOCIATED WITH THIS FILE

472 Meadowland Drive, South Burlington, VT 05403
phone(802)863-3003 toll free(877)863-3003 fax(802)863-3311 www.securshred.com

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

SURVEY NUMBER: 1106-51
NEGATIVE FILE NUMBER: 89 A 95:22
UTM REFERENCES: Zone/Easting/Northing 18/658450/4800600
U.S.G.S. QUAD. MAP: Dorset, Vt. 7.5'
PRESENT FORMAL NAME:
ORIGINAL FORMAL NAME:
PRESENT USE: barn
ORIGINAL USE: barn
ARCHITECT/ENGINEER: unknown
BUILDER/CONTRACTOR: unknown
PHYSICAL CONDITION OF STRUCTURE: Excellent <input type="checkbox"/> Good <input checked="" type="checkbox"/> Fair <input type="checkbox"/> Poor <input type="checkbox"/>
STYLE: vernacular
DATE BUILT: c.1900

COUNTY: Rutland
TOWN: Danby
LOCATION: North of TH-31, approx. .1mi. east of junction with TH-1.
COMMON NAME:
PROPERTY TYPE: barn
OWNER: Ed Lewis
ADDRESS:
ACCESSIBILITY TO PUBLIC: Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE: Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>

GENERAL DESCRIPTION:

Structural System

- Foundation: Stone Brick Concrete Concrete Block
- Wall Structure
 - Wood Frame: Post & Beam Balloon
 - Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - Iron d. Steel e. Other:
- Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Siding Brick Veneer Stone Veneer Bonding Pattern: Other:
- Roof Structure
 - Truss: Wood Iron Steel Concrete
 - Other:
- Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
- Engineering Structure:
- Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 1 1/2

Number of Bays: 20x3 Entrance Location: eave left

Approximate Dimensions: 80'x30'

SIGNIFICANCE: Architectural <input checked="" type="checkbox"/> Historic <input type="checkbox"/> Archeological <input type="checkbox"/>
Historic Contexts:
Level of Significance: Local State National

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

A c. 1900 1½ story gambrel roofed dairy barn with new rear ell and wing. Clapboard siding, slate gambrel roof with bellcast, concrete high drive to main eastern gable wall. Sliding vertical plank barn door gable right, at lower level; two gable front 1/1 windows at main level; one eight light window in gable peak. At main level, eastern gable wall has centered silo of molded, fluted concrete blocks, flanked on each side by ten nine light casement windows. Western gable wall has small center addition with slate gable roof, clapboard siding, and two shed roofed extensions. New windows to the right of the addition; ten original windows to the left. New, freestanding, metal silo to left of gable front. Metal ventilator centered on ridgeline. High concrete foundation. New one story gable roofed rear wing and ell have vertical plank siding and corrugated metal roofs.

RELATED STRUCTURES: (Describe)

A. The present farmhouse, across the street, is a new (c.1950) structure with vinyl siding and asphalt shingle gable roof. Non-contributing due to age.


STATEMENT OF SIGNIFICANCE:

This monumental c. 1900 gambrel roofed dairy barn gives mute testimony to the scope of dairying operations in Danby at the turn of the century. Although it is still in use, the sheer weight of the enormous slate roof has caused certain structural problems that may lead to its eventual collapse.

REFERENCES:

Personal interview, Ed Lewis, owner, 7/18/89

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Holly Hitchcock

ORGANIZATION:

Vt Div. Historic Preservation

DATE RECORDED:

7/20/89



1106-51

89-95

22

Vt. Division for Historic Preservation
Rutland County Danby 7/89
Lewis Barn, 1106-51 W
89-A-95:22 Holly Hitchcock

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

SURVEY NUMBER:

1106-52

NEGATIVE FILE NUMBER:

89A95: 11,12, 83-A-392 #20

UTM REFERENCES:

Zone/Easting/Northing

18/658000/4800130

U.S.G.S. QUAD. MAP:

Wallingford, Vt. 15'

PRESENT FORMAL NAME:

ORIGINAL FORMAL NAME:

PRESENT USE: farm

ORIGINAL USE: farm

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

unknown

PHYSICAL CONDITION OF STRUCTURE:

Excellent Good

Fair Poor

STYLE: vernacular

DATE BUILT:

c. 1890

COUNTY:	Rutland
TOWN:	Danby
LOCATION:	west of TH-2, approx, .1 mile south of junction with TH-26.
COMMON NAME:	Fiske Place
PROPERTY TYPE:	house
OWNER:	Taconic Foundation
ADDRESS:	
ACCESSIBILITY TO PUBLIC:	Yes <input type="checkbox"/> No <input type="checkbox"/> Restricted <input checked="" type="checkbox"/>
LEVEL OF SIGNIFICANCE:	Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>

GENERAL DESCRIPTION:

Structural System

- Foundation: Stone Brick Concrete Concrete Block
- Wall Structure
 - Wood Frame: Post & Beam Balloon
 - Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - Iron d. Steel e. Other:
- Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Siding Brick Veneer Stone Veneer Bonding Pattern: Other:
- Roof Structure
 - Truss: Wood Iron Steel Concrete
 - Other:
- Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
- Engineering Structure:
- Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 1 1/2

Number of Bays: 4 x 2

Approximate Dimensions: 6' x 12'

Entrance Location: L-Plan

SIGNIFICANCE: Architectural Historic Archeological

Historic Contexts: _____ Level of Significance: Local State National

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

A vernacular style gable roofed farmhouse with southern ell and open front porch. Box cornice, simple corner boards. 2/2 sash with simple surrounds. Eave center entry on ell, flanked by 2/2 sash; two eave kneewall windows above, gable dormer centered on front eave slope. Open porch has shed roof, straight posts. Equal height main block has three 2/2 windows along front gable, one at second story level. Concrete faced stone foundation, interior brick chimneys on right front and left ridgeline of ell.

RELATED STRUCTURES: (Describe)

A. A 1½ story ground level carriage barn with clapboard siding and slate gable roof. C. 1890. 40'x16'. Box cornice, corner boards. Paired eave front sliding vertical plank carriage doors. Haydoor at northern gable peak and sash on southern gable peak are boarded over. One story gable roofed ell is centered on rear eave wall. Rubblestone foundation.


STATEMENT OF SIGNIFICANCE:

The Fiske place, and the farm to the immediate north, the Hilliard place, became intimately associated due to intermarriage between the two families. Thereafter, it functioned as a tenant farm. The unpretentious main house is surrounded by exceptional pastureland and is impeccably maintained by the Taconic Foundation.

REFERENCES:

personal interview, Lynn Bondurant, gen. manager of Smokey House Project for Taconic Foundation, 7/21/89

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Holly Hitchcock

ORGANIZATION:

Vt. Div. Historic Preservation

DATE RECORDED:

10/12/89

RELATED STRUCTURES CONTINUED: 1106-52

B. A 1½ story ground level dairy barn with clapboard siding and slate gable roof. C. 1920. 40'x16'. Sliding double leaf vertical plank doors at eave left; one, centered, six light sash at eave right. Stone foundation.

C. A 1½ story barn with clapboard siding and slate gable roof. C. 1900. 26'x20'. Eave right sliding vertical plank barn doors; eave left vertical plank pass door. New two light sash at ground level and gable peak of eastern gable wall. Shed roofed addition along rear eave wall has corrugated metal roof, clapboard siding. Free standing metal silo on eastern gable wall. Stone foundation.



1106-52

Vt. Division for Historic Preservation
Rutland County Danby 7/89
Fiske House, 1106-52 W
89-A-95:11 Holly Hitchcock

89-95
11

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

SURVEY NUMBER: 1106-53
NEGATIVE FILE NUMBER: 89A95:9,10, 83-A-389:0
UTM REFERENCES: Zone/Easting/Northing 18/657920/4800690
U.S.G.S. QUAD. MAP: Dorset, Vt. 7.5'
PRESENT FORMAL NAME: Smokey House Project
ORIGINAL FORMAL NAME:
PRESENT USE: office
ORIGINAL USE: house
ARCHITECT/ENGINEER:
BUILDER/CONTRACTOR: unknown
PHYSICAL CONDITION OF STRUCTURE: Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor <input type="checkbox"/>
STYLE: Greek Revival
DATE BUILT: c. 1850

COUNTY: Rutland
TOWN: Danby
LOCATION: West of TH-.2, at junction with TH.31.
COMMON NAME: Hilliard House
PROPERTY TYPE: house
OWNER: Taconic Foundation
ADDRESS:
ACCESSIBILITY TO PUBLIC: Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE: Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>

GENERAL DESCRIPTION:

Structural System

- Foundation: Stone Brick Concrete Concrete Block
- Wall Structure
 - Wood Frame: Post & Beam Balloon
 - Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - Iron d. Steel e. Other:
- Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Siding Brick Veneer Stone Veneer Bonding Pattern: Other:
- Roof Structure
 - Truss: Wood Iron Steel Concrete
 - Other:
- Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
- Engineering Structure:
- Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 1 1/2

Number of Bays: 5x2 Entrance Location Classic Cottage

Approximate Dimensions: 24'x16'

SIGNIFICANCE: Architectural <input checked="" type="checkbox"/> Historic <input type="checkbox"/> Archeological <input type="checkbox"/>
Historic Contexts:
Level of Significance: Local State National

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

A 1½ story Greek Revival style Classic Cottage residence with two successive one story wings. 5x2 bays. 24'x16'. Clapboarded, wide molded cornice with returns, panelled corner pilasters. Recessed eave center entry has full entablature, and 2/3 sidelights. Three two-light kneewall windows. 2/2 sash throughout. Northern wing has eave center entry, flanked by 2/2 sash, and deepoverhang over brick patio. It connects main block to second northern wing with one new two-light casement centered on eastern wall and panelled corner pilasters. Portion of main block gable has been slightly extended on western eave wall. Concrete faced stone foundation, slate roof. Exterior brick chimney on southern gable wall, interior brick chimneys at right of both main block and second northern wing.

RELATED STRUCTURES: (Describe)

A. A gable roofed ground level dairy barn with wing and shed additions. 40'x60'. C. 1900. Clapboarded, slate roof. Rear gable wall has three, evenly spaced, sliding vertical plank livestock doors, with diagonal supports; hoist above. Front gable wall has gable left vertical plank passdoor, beneath small haydoor; one story wing at gable right. Wing has clapboard siding,


STATEMENT OF SIGNIFICANCE:

Originally the Hilliard Farm, this c. 1850 house and several outbuildings were purchased by the Taconic Foundation about fifteen years ago. Now the site of the Smokey House Project, which provides a practical agriculturally oriented education for disadvantaged youths. The buildings have been impeccably maintained and or restored. Although, in some cases, the functions have changed, the structures retain their original character.

REFERENCES:

personal interview, Lynn Bondurant, gen. mgr. of Smokey House Project, Taconic Foundation, 7/21/89

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Holly Hitchcock

ORGANIZATION:

Vt Div. Historic Preservation

DATE RECORDED:

10/11/89

RELATED STRUCTURES CONTINUED: 1106-53

slate roof, sliding double leaf vertical plank doors gable left, sliding vertical plank passdoor gable right. Two fixed four light windows on southern eave wall. Main block has shed roofed additions the the length of both eave walls, with twelve fixed four-light windows. Raised concrete foundation at additions.

B. A 2½ story, gable roofed, c1900 barn, (now woodworking shop), with clapboard siding and slate roof. 20'x40'. Box cornice. Gable center hinged double leaf vertical plank doors, beneath second floor vertical plank hay-door, and four light gable peak window. New gable left pass door. Four new 1/1 windows at both ground and second floor levels, on both eave walls. Concrete faced stone foundation.

C. A one story gable roofed shed with rubblesotne walls and slate gable roof. 8'x10'. C. 1900. Gable center vertical plank pass door. 2/2 sash along both eave walls, and on rear gable wall. Stone foundation.



1106-53

89-95

9

Vt. Division for Historic Preservation
Rutland County Danby 7/89
Hilliard House, 1106-53 SW
89-A-95:9 Holly Hitchcock



1106-53

Vt. Division for Historic Preservation
Rutland County Danby 7/89
Hilliard Barn, 1106-53 W
89-A-95:10 Holly Hitchcock

89-95

10

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

SURVEY NUMBER:
1106-54

NEGATIVE FILE NUMBER:
89 A 95:5,6,7,8

UTM REFERENCES:
Zone/Easting/Northing
18/657970/4801210

U.S.G.S. QUAD. MAP:
Dorset, Vt. 7.5'

PRESENT FORMAL NAME:

ORIGINAL FORMAL NAME:

PRESENT USE: apartments

ORIGINAL USE: house

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:
Excellent Good
Fair Poor

STYLE: vernacular

DATE BUILT: c. 1820

COUNTY: Rutland

TOWN: Danby

LOCATION: West of TH-25, approx. .2 mi.
south of junction with TH-1.

COMMON NAME:
Herrick House

PROPERTY TYPE:

OWNER: Taconic Foundation

ADDRESS:

ACCESSIBILITY TO PUBLIC:
Yes No Restricted

LEVEL OF SIGNIFICANCE:
Local State National

GENERAL DESCRIPTION:

Structural System

- Foundation: Stone Brick Concrete Concrete Block
- Wall Structure
 - Wood Frame: Post & Beam Balloon
 - Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - Iron d. Steel e. Other:
- Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Siding Brick Veneer Stone Veneer Bonding Pattern: Other:
- Roof Structure
 - Truss: Wood Iron Steel Concrete
 - Other:
- Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
- Engineering Structure:
- Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 2½

Number of Bays: 5x2

Approximate Dimensions: 26'x14'

Entrance Location: Georgian Plan

SIGNIFICANCE: Architectural Historic Archeological

Historic Contexts:

Level of Significance:
Local State National

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

A 2½ story Georgian Plan, vernacular-Federal residence with 1½ story ell. 5x2 bays. 26'x14'. Clapboard siding, molded cornice with returns, corner pilasters. Eave central entry with full entablature and pilasters. Sash are 12/12 at second floor level; 2/2 at ground floor. Secondary gable center entry faces road. 5x2 bay ell has eave central entry, flanked by two and two 2/2 windows. below four kneewall windows. Small, flat roofed open porch fronts rear entrance at intersection of main block and ell. Concrete faced stone foundation, slate roofs, interior brick chimneys on main block and ell. Main block chimney has corbelled "collar".

RELATED STRUCTURES: (Describe)

A. c1900 a 1½ story gable roofed farm structure with clapboard siding and slate roof. Sliding vertical plank barn door on front eave wall. New two light horizontal casement on southern gable wall, beneath small gable peak window. Structure has open storage wing with straight posts to the north. B. Formerly two separate structures,


STATEMENT OF SIGNIFICANCE:

Chose's map of 1854 indicates I.H. Vail as the owner of this c. 1820 vernacular Federal farmhouse; however, it is locally known as the Old Herrick House. Its location, just south of Danby Four Corners, was the site of some of the earliest building in Danby. Now owned by the Taconic Foundation, the function of the well-maintained house and outbuildings has changed.

REFERENCES:

Personal interview, Lynn Bondurant, general manager- Taconic Foundation
Chose's Map, 1854

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Holly Hitchcock

ORGANIZATION:

Vt. Div. Historic Preservation

DATE RECORDED:

7/18/89

RELATED STRUCTURES CONTINUED:

a c.1900 barn and carriage shed are now connected by a one story ell. The roadside gable roofed main block is 4x2 bays, 20'x16'. Clapboard siding, corner boards, box cornice, slate roof. Two sliding vertical plank barn doors face road on western eave wall. Two gable wall windows are two light casement, with small casement in gable peak. Small shed roofed shed with vertical plank front pass door to the right. One story gable roofed ell with clapboard siding, slate roof, and regularly spaced four light casement connects barn to 1½ story gable roofed carriage barn, now auto shop. Carriage barn is 24'x18', 4x2 bays. Four evenly spaced replacement windows at ground level and kneewall on both eave walls. Two new overhead garage doors at southern gable wall. Carriage barn has clapboard siding and slate roof. Stone foundation.



1106-54

Vt. Division for Historic Preservation
Rutland County Danby 7/89
Herrick House, 1106-54 N
89-A-95:6 Holly Hitchcock

89-95

6

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

SURVEY NUMBER: 1106-55
NEGATIVE FILE NUMBER: 89A93:18-22; 83-A-389
UTM REFERENCES: Zone/Easting/Northing 18/658210/4801850
U.S.G.S. QUAD. MAP: Wallingford, VT. 15'
PRESENT FORMAL NAME:
ORIGINAL FORMAL NAME:
PRESENT USE: house/office
ORIGINAL USE: house
ARCHITECT/ENGINEER: unknown
BUILDER/CONTRACTOR: unknown
PHYSICAL CONDITION OF STRUCTURE: Excellent <input type="checkbox"/> Good <input checked="" type="checkbox"/> Fair <input type="checkbox"/> Poor <input type="checkbox"/>
STYLE: vernacular
DATE BUILT: c.1890

COUNTY: Rutland
TOWN: Danby
LOCATION: east of SA-2, at junction with SA-1. Danby Four corners.
COMMON NAME:
PROPERTY TYPE: house
OWNER: Margaret L. Coburn ADDRESS:
ACCESSIBILITY TO PUBLIC: Yes <input type="checkbox"/> No <input type="checkbox"/> Restricted <input checked="" type="checkbox"/>
LEVEL OF SIGNIFICANCE: Local <input type="checkbox"/> State <input type="checkbox"/> National <input type="checkbox"/>

GENERAL DESCRIPTION:

Structural System

- Foundation: Stone Brick Concrete Concrete Block
- Wall Structure
 - Wood Frame: Post & Beam Balloon
 - Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - Iron d. Steel e. Other:
- Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Siding Brick Veneer Stone Veneer Bonding Pattern: Other:
- Roof Structure
 - Truss: Wood Iron Steel Concrete
 - Other:
- Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
- Engineering Structure:
- Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 1 1/2

Number of Bays: 2x3 Entrance Location: e11

Approximate Dimensions: 14'x20'

SIGNIFICANCE: Architectural <input checked="" type="checkbox"/> Historic <input type="checkbox"/> Archeological <input type="checkbox"/>
Historic Contexts:
Level of Significance: Local State National

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

House with rear wing, and side ell fronted by a Queen Anne style porch. Molded cornice, simple corner boards. Sash are predominately 1/1, with many newly placed and variously sized windows throughout. Gable left bay window has molded cornice, 1/1 sash. 1/1 sash at right of bay window, and above. Ell deteriorated Queen Anne style porch with slate shed roof, spindle valance, scrollsawn brackets, and new straight supports. Brick chimney on northern eave wall; new paired 2/2 sash at eave left. Exterior concrete block chimney is centered on rear gable wall. One story gable roofed wing at left rear has sheet metal roof, vertical plank siding, eave wall pass doors, 1/1 sash, and central brick chimney.

RELATED STRUCTURES: (Describe)

A. A 1 1/2 story gable roofed bank barn with corrugated metal roof and clapboard siding. C. 1890. 40'x30'. Box cornice, corner boards. Eave center sliding vertical plank door; eave left vertical plank pass door. Small window in western gable peak is lacking sash. Paired 1/1 sash in raised foundation of western gable wall.


STATEMENT OF SIGNIFICANCE:

This c. 1890 structure is a good example of a modest cottage type farmhouse, and fortunately, retains its contemporaneous carriage barn, and various outbuildings. Local residents claim that a greatly deteriorated structure to the south was once a related granary. The property is located at a once major crossroads; before Danby Four Corners became three corners. The now disused eastern route passes through this property.

REFERENCES:

personal interview, Margaret L. Coburn , owner, 7/13/89

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Holly Hitchcock

ORGANIZATION:

VT Div Historic Preservation

DATE RECORDED:

11/9/89

One story shed roofed c.1920 milkhouse along southern eave wall has sheet metal roof, clapboard siding, empty window on western wall. Small one story western wing has slate gable roof, clapboard siding, eave right pass door and two boarded over windows on western gable wall. Possibly predates house.

B. A 1½ story gable roofed dairy barn with corrugated metal roof, novelty siding.

C. 1920. 40'x30'. Box cornice, corner boards. Eave center entry lacks barn door. Eight small four-light windows are at right of entry. Gable roofed dormer is centered on western gable slope. Northern gable wall abuts southern wall of Barn A. addition.

C. A 1½ story gable roofed carriage barn with slate roof and clapboard siding. C. 1890. 20'x30. Box cornice, corner boards. Paired sliding garage doors, gable front, although historic, are replacements. Unusual eight light window with triangular sash., in gable peak, in a field of shinglework. Three windows along northern eave wall are boarded over.



1105-55

89-93

18

Vt. Division for Historic Preservation
Rutland County Danby 7/89
Coburn House, 1106-55 E
89-A-93:18 Holly Hitchcock

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

SURVEY NUMBER:

1106-57

NEGATIVE FILE NUMBER:

89A93:16,23; 83-A-389 #3

UTM REFERENCES:

Zone/Easting/Northing

18/658160/4801830

U.S.G.S. QUAD. MAP:

Dorset, Vt. 7.5'

PRESENT FORMAL NAME:

ORIGINAL FORMAL NAME:

PRESENT USE: store

ORIGINAL USE: store

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:

Excellent Good

Fair Poor

STYLE: Italianate

DATE BUILT:

c. 1860

COUNTY:	Rutland
TOWN:	Danby
LOCATION:	south of TH-1, at junction with TH-2. Danby Four Corners.
COMMON NAME:	Danby Four Corners Store
PROPERTY TYPE:	store
OWNER:	Harry and Linda Ralph
ADDRESS:	
ACCESSIBILITY TO PUBLIC:	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE:	Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone Brick Concrete Concrete Block
2. Wall Structure
 - a. Wood Frame: Post & Beam Balloon
 - b. Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - c. Iron d. Steel e. Other:
3. Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Siding Brick Veneer Stone Veneer Bonding Pattern: Other:
4. Roof Structure
 - a. Truss: Wood Iron Steel Concrete
 - b. Other:
5. Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
6. Engineering Structure:
7. Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast

With Parapet With False Front Other:

Number of Stories: 1 1/2

Number of Bays: 2x2

Entrance Location: eave left

Approximate Dimensions: 30'x18'

SIGNIFICANCE: Architectural Historic Archeological

Historic Contexts:

Level of Significance:
Local State National

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

A 1½ story Italianate style gable roofed store with rear ell and shed additions. 30'x18'. Clapboard siding, molded cornice, simple corner boards. Italianate style storefront at left of northern eave wall has recessed central doorway beneath bracketed entablature. Bracketed entablature repeats over entry door to the right. Gable sash is 2/2 with new multipane window at first floor level. Small rear gable roofed ell, with shed roofed additions on both eave walls, faces new open deck. Concrete faced stone foundation, asphalt shingle roof, interior brick chimney at left of ridge line. Ell and shed additions have slate roofs.

RELATED STRUCTURES: (Describe)


STATEMENT OF SIGNIFICANCE:

There has been a store at this site, serving Danby Four Corners, since 1790. The present c. 1860 structure has passed through a succession of owners but retains its Italianate style storefront. Its presence serves as a reminder of Danby Four Corners former preeminence, before being eclipsed by Danby Borough.

REFERENCES:

personal interview, Linda Coburn Ralph, owner, 7/6/89

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Holly Hitchcock

ORGANIZATION:

Vt. Div. Historic Preservation

DATE RECORDED:

7/7/89



1106-57

89-93

16

Vt. Division for Historic Preservation
Rutland County Danby 7/89
Ralph's Store, 1106-57 SW
89-A-93:16 Holly Hitchcock

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

SURVEY NUMBER: 1106-58
NEGATIVE FILE NUMBER: 89-A93: 17
UTM REFERENCES: Zone/Easting/Northing 18/658140/4801840
U.S.G.S. QUAD, MAP: Wallingford, VT. 15'
PRESENT FORMAL NAME:
ORIGINAL FORMAL NAME:
PRESENT USE: house
ORIGINAL USE: carriage barn
ARCHITECT/ENGINEER: unknown
BUILDER/CONTRACTOR: unknown
PHYSICAL CONDITION OF STRUCTURE: Excellent <input type="checkbox"/> Good <input checked="" type="checkbox"/> Fair <input type="checkbox"/> Poor <input type="checkbox"/>
STYLE: vernacular-Italianate
DATE BUILT: c.1880

COUNTY: Rutland
TOWN: Danby
LOCATION: south of SA1 approx, .1 miles west of Danby Four Corners.
COMMON NAME:
PROPERTY TYPE: carriage barn
OWNER: Ralph Loomis, Jr.
ADDRESS:
ACCESSIBILITY TO PUBLIC: Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE: Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>

GENERAL DESCRIPTION:

Structural System

- Foundation: Stone Brick Concrete Concrete Block
- Wall Structure
 - Wood Frame: Post & Beam Balloon
 - Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - Iron d. Steel e. Other:
- Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Siding Brick Veneer Stone Veneer Bonding Pattern: Other:
- Roof Structure
 - Truss: Wood Iron Steel Concrete
 - Other:
- Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
- Engineering Structure:
- Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 1 1/2

Number of Bays: 3x3 Entrance Location: eave

Approximate Dimensions: 36'x30'

SIGNIFICANCE: Architectural <input checked="" type="checkbox"/> Historic <input type="checkbox"/> Archeological <input type="checkbox"/>
Historic Contexts:
Level of Significance: Local State National

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

A 1½ story gable roofed house, formerly a carriage barn, with rear ell. Box cornice, simple corner boards. Eave center vertical plank segmental arched carriage door is flanked by lower vertical plank carriage door on the left, and new overhead garage door on the right. Three evenly spaced new octagonal windows at kneewall. Eastern gable center pass door with segmental arched lintelboard has new 1/1 sash at left, 6/6 sash at right, and two 6/6 windows above. Exterior concrete block chimney is immediately right of entry. Western gable wall has new gable right entry, gable left 6/6 sash, and 6/6 sash above; gable center exterior concrete block chimney. One story gable roofed ell at left rear has slate roof, clapboard siding, eastern eave center entry, with 6/6 sash at right. Concrete faced stone foundation.

RELATED STRUCTURES: (Describe)


STATEMENT OF SIGNIFICANCE:

This c. 1850 structure originally housed a carriage and livery business run by the owners of the adjacent store. Although it has been converted to a residence, the three eave front carriage doors reveal its original function. The structure built during the last few years of Danby Four corners' pre-eminence, before the rise of marble quarrying in Danby Borough.

REFERENCES:

Personal interview, Maragaret Coburn, former owner,
7/13/89

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Holly Hitchcock

ORGANIZATION:

VT Div. Historic Preservation

DATE RECORDED:

11/9/89



1106-58

89-93

17

Vt. Division for Historic Preservation
Rutland County Danby 7/89
Loomis House, 1106-58 SW
89-A-93:17 Holly Hitchcock

Note: Map in publication is inaccurate:
#57 & 58 should be left of #56 & 55,
just south of TH-1.

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

SURVEY NUMBER: 1106-59
NEGATIVE FILE NUMBER: 89A93:24 83-A-389 #2
UTM REFERENCES: Zone/Easting/Northing 18/658080/4801840
U.S.G.S. QUAD. MAP: Dorset, Vt. 7.5'
PRESENT FORMAL NAME:
ORIGINAL FORMAL NAME:
PRESENT USE: town hall
ORIGINAL USE: town hall
ARCHITECT/ENGINEER:
BUILDER/CONTRACTOR: Town of Danby
PHYSICAL CONDITION OF STRUCTURE: Excellent <input type="checkbox"/> Good <input checked="" type="checkbox"/> Fair <input type="checkbox"/> Poor <input type="checkbox"/>
STYLE: vernacular
DATE BUILT: 1914

COUNTY: Rutland
TOWN: Danby
LOCATION: south of TH-1, approx. .2 miles west of Danby Four Corners
COMMON NAME:
PROPERTY TYPE: town hall
OWNER: Town of Danby
ADDRESS:
ACCESSIBILITY TO PUBLIC: Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE: Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>

GENERAL DESCRIPTION:

Structural System

- Foundation: Stone Brick Concrete Concrete Block
- Wall Structure
 - Wood Frame: Post & Beam Balloon
 - Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - Iron d. Steel e. Other:
- Wall Covering: Clapboard Board & Batten Wood Shingle
Shiplap Novelty Asbestos Shingle Sheet Metal
Aluminum Asphalt Siding Brick Veneer Stone Veneer
Bonding Pattern: Other:
- Roof Structure
 - Truss: Wood Iron Steel Concrete
 - Other:
- Roof Covering: Slate Wood Shingle Asphalt Shingle
Sheet Metal Built Up Rolled Tile Other:
- Engineering Structure:
- Other:

Appendages: Porches Towers Cupolas Dormers Chimneys
Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel
Jerkinhead Saw Tooth With Monitor With Bellcast
With Parapet With False Front Other:

Number of Stories: 1 1/2

Number of Bays: 3x5 Entrance Location: gable center

Approximate Dimensions: 25'x50'

SIGNIFICANCE: Architectural <input type="checkbox"/> Historic <input checked="" type="checkbox"/> Archeological <input type="checkbox"/>
Historic Contexts:
Level of Significance: Local State National

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

A 1½ story vernacular style gable roofed town hall built in 1914. 3x5 bays. 25'x50'. Sheathed in stucco to the gable line, wood shingles above. Metal gable front entrance door is inset in plywood area describing original larger entrance; flanked by 6/6 sash. Entrance is reached by stone steps with wooden handrail. Cornerstone to right of steps says "1914". Double 6/6 windows on right eave wall, at second floor level, flank central entry with iron platform and steps. Basement six light-windows correspond to main floor sash placement. Concrete foundation, slate roof, exterior brick chimney at left of rear gable wall.


RELATED STRUCTURES: (Describe)

STATEMENT OF SIGNIFICANCE:

This 1914 town hall is one of the only twentieth century structures in Danby Four Corners. It is a product of the modest development spurred by a revival in the marble industry and checked by the Great Depression.

REFERENCES:

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:
Holly Hitchcock

ORGANIZATION:
Vt Div. Historic Preservation

DATE RECORDED:
7/7/89



1106-59

89-93
Vt. Division for Historic Preservation
Rutland County Danby 7/89
Town Hall, 1106-59 SE
89-A-93:24 Holly Hitchcock
24

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

SURVEY NUMBER:

1106-60

NEGATIVE FILE NUMBER:

89A93:14,15; 83-A-391 #15

UTM REFERENCES:

Zone/Easting/Northing

18/657680/4802000

U.S.G.S. QUAD. MAP:

Dorset, Vt. 7.5'

PRESENT FORMAL NAME:

ORIGINAL FORMAL NAME:

PRESENT USE: house

ORIGINAL USE: house

ARCHITECT/ENGINEER:

unknown

BUILDER/CONTRACTOR:

Dr. Tolman

PHYSICAL CONDITION OF STRUCTURE:

Excellent Good

Fair Poor

STYLE: Vernacular

DATE BUILT:

c. 1820

COUNTY: Rutland

TOWN: Danby

LOCATION: north of TH-.1, approx. .5 miles west of Danby Four Corners.

COMMON NAME:

PROPERTY TYPE: house

OWNER: Marvin Gates

ADDRESS:

ACCESSIBILITY TO PUBLIC:

Yes No Restricted

LEVEL OF SIGNIFICANCE:

Local State National

GENERAL DESCRIPTION:

Structural System

- 1. Foundation: Stone Brick Concrete Concrete Block
- 2. Wall Structure
 - a. Wood Frame: Post & Beam Balloon
 - b. Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - c. Iron d. Steel e. Other:
- 3. Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Siding Brick Veneer Stone Veneer Bonding Pattern: Other:
- 4. Roof Structure
 - a. Truss: Wood Iron Steel Concrete
 - b. Other:
- 5. Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
- 6. Engineering Structure:
- 7. Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 1 1/2

Number of Bays: 2x5

Entrance Location: gable center

Approximate Dimensions: 20'x24'

SIGNIFICANCE: Architectural Historic Archeological

Historic Contexts:

Level of Significance:

Local State National



1106-60

89-93

14

Vt. Division for Historic Preservation
Rutland County Danby 7/89
Gates House, 1106-60 NW
89-A-93:14 Holly Hitchcock

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

SURVEY NUMBER:

1106-61

NEGATIVE FILE NUMBER:

89A94.3.4: 85-A-569 #21

UTM REFERENCES:

Zone/Easting/Northing

18/661650/4804170

U.S.G.S. QUAD. MAP:

Dorset, Vt. 7.5'

PRESENT FORMAL NAME:

ORIGINAL FORMAL NAME:

Nichols Farm

PRESENT USE: house

ORIGINAL USE: house

ARCHITECT/ENGINEER:

unknown

BUILDER/CONTRACTOR:

D. Nichols

PHYSICAL CONDITION OF STRUCTURE:

Excellent Good

Fair Poor

STYLE: vernacular

DATE BUILT:

c. 1800

COUNTY:	Rutland
TOWN:	Danby
LOCATION:	west of Th-19, approx, .4 miles south of junction with U.S.7.
COMMON NAME:	Old King Place
PROPERTY TYPE:	house
OWNER:	Lillian King
ADDRESS:	
ACCESSIBILITY TO PUBLIC:	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE:	Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone Brick Concrete Concrete Block
2. Wall Structure
 - a. Wood Frame: Post & Beam Balloon
 - b. Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - c. Iron d. Steel e. Other:
3. Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Siding Brick Veneer Stone Veneer Bonding Pattern: Other:
4. Roof Structure
 - a. Truss: Wood Iron Steel Concrete
 - b. Other:
5. Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
6. Engineering Structure:
7. Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 1 1/2

Number of Bays: 3x2

Entrance Location: cape cod

Approximate Dimensions: 24'x20'

SIGNIFICANCE: Architectural Historic Archeological

Historic Contexts:

Level of Significance:
Local State National

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

A 1½ story vernacular style Cape Cod type dwelling, with shed roofed addition at the left rear. 3x2 bays. 24'x20'. Woodshingled to gable line, clapboarded abpve. Cornice details encased in new metal drip edge. Eave central vertical plank entry door is flanked by 2/2 sash at eaveline. Right gable wall has small aquare gable end windows flanking central 2/2 window; two 2/2 windows below. Shed addition with asphalt shingle siding and rolled roof fronts secondary entrance to main block. Stone foundation faced by concrete coping, rolled roofing, central brick chimney.

RELATED STRUCTURES: (Describe)


A 1½ story c1830 gable roofed early barn with shed roofed addition. Flushboard siding, slate roof. Gable center open bay, lacking door, beneath gable peak hinged haydoor. Addition to the right has asphalt shingle siding, rolled roof, hinged vertical plank pass door on front wall. Cobblestone foundation.

STATEMENT OF SIGNIFICANCE:

This c. 1800 structure is believed by many locals to be the oldest house in Danby. Its broad gable roof, square gable end windows, and central chimney are characteristic of early Cape Cod type dwellings. Known locally as the Nichols Farm, it retains only one of the original outbuildings.

REFERENCES:

personal interviews- Lillian King, owner Paul Pierce, life-long resident; 7/12/89



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Holly Hitchcock

ORGANIZATION:

Vt Div. Historic Preservation

DATE RECORDED:

7/13/89



1106-61

89-94

4

Vt. Division for Historic Preservation
Rutland County Danby 7/89
King House, 1106-61 NW
89-A-94:4 Holly Hitchcock